

Matador '5' Federal No. 1

P&A Procedure

August 21, 1997

35. Contact and file all reports to appropriate regulatory agencies.

Cement Plug Program			
Cement Plug	Bottom (ft)	Top (ft)	Reason for Plug
1	6200	6060	50' in/50' out csg cut
2	5205	5100	8-5/8" csg shoe
3	3225	3125	Bottom of Salt
4	485	383	13-3/8" csg shoe
5	125	surface	Surface Plug


By: B.L. Williams
Production Engineer


Approved: G.D. Muse
NW Operations Production Superintendent

RECEIVED
1997 AUG 21 P 1:43
BUREAU OF LAND MGMT.
HOBBBS, NEW MEXICO