

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31337
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name Merit Record 35
8. Well No. 1
9. Pool name or Wildcat <i>Wildcat</i> <i>Pearl, N. (Wolfcamp)</i>

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Mitchell Energy Corp.

3. Address of Operator
P.O. Box 4000 The Woodlands, TX 77387-4000

4. Well Location
Unit Letter P : 990 Feet From The South Line and 990 Feet From The East Line
Section 35 Township 19S Range 35E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3672' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.
MIRU PU. POOH w/rods & 2 3/8" tbg. RIH w/CIBP & set @ 11,200'. Dump 30' of cmt on top. Load hole w/9.5# mud. RIH w/csg cutter & cut off 5 1/2" csg @ + 10,100'. POOH w/5 1/2" csg, RIH w/tbg & spot 100' cmt plug across csg cut off top @ + 10,100'. Pull up & spot 100' plug @ 7500'. PU & set 100' cmt plug across 8 5/8" shoe @ 5132'. PU & set 100' cmt plug in 8 5/8" csg @ top of salt from 1700'-1800'. Spot 50 sx surface plug & erect P & A MARKER. RDMO PU.

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE BEGINNING OF
PLUGGING OPERATIONS FOR THE C-103
TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.
SIGNATURE James Blount TITLE Engineer DATE 4-30-92
TYPE OR PRINT NAME James Blount TELEPHONE NO. 915-682-5396

(This space for State Use)
APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

MAY 04 '92