

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-35119
5. Indicate Type of Lease	STATE FEE <input checked="" type="checkbox"/>
6. State Oil / Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT (FORM C-101) FOR SUCH PROPOSALS.

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER NEW WELL <input type="checkbox"/>	7. Lease Name or Unit Agreement Name	J R PHILLIPS
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.	8. Well No.	15
3. Address of Operator	205 E. Bender, HOBBS, NM 88240	9. Pool Name or Wildcat	MONUMENT ABO
4. Well Location	Unit Letter <u>C</u> : <u>650</u> Feet From The <u>NORTH</u> Line and <u>1865</u> Feet From The <u>WEST</u> Line Section <u>6</u> Township <u>20-S</u> Range <u>37-E</u> N M P M <u>LEA</u> COUNTY		
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3565'		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	COMPLETION <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-27-00: MIRU KEY #174. NUBOP. TAG CMT @ 3800'. DRLG 3800-3950,4271,4830. DRLD DV @ 4330. TIH W/TBG & TAG CMT @ 6885. DRLD 6885,7016. DRLD FC & 20' CMT. DRLD FLOAT SHOE @ 7070. WASH SAND FR 7071-7350. 10-01-00: TAG SAND @ 7350. WASH SAND 7350-7600. TIH W/2 7/8" TBG. 10-02-00: PKR @ 6899. SN @ 6891. 10-03-00: ACID FRAC ABO FORM W/20,000 GALS 20% HCL & 5000 GALS WF 110. 10-24-00: SITP-580#. OPEN UP ON 25/64 CHOKE. FLOW DN TO 80#. 10-6-00: REL PKR @ 6899. PMP 65 BBLS BRINE WTR DN TBG. PMP 55 BBLS BRINE WTR DN ANNULUS. FREE POINT TBG. STUCK FR 7558-7523. TIH W/CHEM CUTTER: & CUT @ 6988. TIH W/TBG. 10-07-00: JAR FISH LOOSE. 10-08-00: TIH W/TBG TO 7037. TIH TO 6982. TIH TO 7037. DRLD 7037-7045. BTM CF CSG @ 7070. 10-09-00: DRLG 7045-7079. FELL THRU BRIDGE @ 7079. TIH W/TBG TO 7454. TIH W/TBG & Tag @ 7447. C/o to 7452. TIH W/MA, SN, TBG, TAC. SN @ 7031, TAC @ 6997. NDBOP. NUTBG. 10-11-00: PU PUMP & RDS. SPACE OUT HANG OFF. RIG DOWN. 10-12-00: SET PUMPING UNIT. 10-14-00: PUT PUMP ON LINE @ 1445 HRS. PUMPING & TESTING 10-15/10-26-00.

1-07-01: ON 24 HR OPT. PUMPING 59 BO, 216 BW, & 222 MCF.

FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 1/30/01

TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use)

APPROVED _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: _____