Submit 3 Copies To Appropriate District	State of Ne	w Mexico			Form C-103	
Office District I	Energy, Minerals and	d Natural Res	sources	WELL ADING	Revised March 25, 1999	٦
1625 N. French Dr., Hobbs, NM 88240 District II				WELL API NO. 30-025-0	7809	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION			5. Indicate Type		1
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.			STATE	FEE X	
District IV	Santa Fe, NM 87505			6. State Oil &	Gas Lease No.	7
1220 S. St. Francis Dr., Santa Fe, NM 87505						
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name of	or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				72.00	en Meter Uni	#
PROPOSALS.)					-	
1. Type of Well:				Fred Turn	er Jr. A	
Oil Well X Gas Well Other				7		4
2. Name of Operator				7. Well No.	3 1/4	
Amerada Hess Corporation 3. Address of Operator				8. Pool name o		\dashv
P. O. Box 840, Seminole, Texas 79360					bo East (56630)	
4. Well Location						
						
Unit Letter A: 660	feet from the Nor	th line a	nd <u>660</u>	feet from the_	<u>East</u> line	
Section 19	Township 20S	Range	38E	NMPM Lea	a County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.)						
3560' GR						
11. Check App.	ropriate Box to Indic	cate Nature	of Notice, l	Report or Other	r Data	
NOTICE OF INTE				SEQUENT_RE		
PERFORM REMEDIAL WORK 📗 PI	LUG AND ABANDON] REM	EDIAL WOF		ALTERING CASING	l
TEMPORARILY ABANDON CI	HANGE PLANS [] сом	IMENCE DRIL	LING OPNS.	PLUG AND	
PULL OR ALTER CASING MULTIPLE CASING TEST A				р П	ABANDONMENT	
-	OMPLETION [ENT JOB	.5		
OTHER:	[_ отні	ER:	Progress Report	. x	ζ.
12. Describe proposed or completed op	erations. (Clearly state a	all pertinent d	etails, and giv	e pertinent dates,	including estimated date of	of
starting any proposed work). SEE R	RULE 1103. For Multipl	le Completion	s: Attach we	llbore diagram of	proposed completion or	
recompilation.						
7-1 thru 10-09-2002					:	
MIRU Key Energy Syc. pulling unit. Re	emoved wellhead & insta	alled BOP. TI	IH w/4-3/4" b	it, tagged CIBP a	t 5145' & press. tested csg	
MIRU Key Energy Svc. pulling unit. Removed wellhead & installed BOP. TIH w/4-3/4" bit, tagged CIBP at 5145' & press. tested csg. to 500 PSI. Held OK. Drld. out CIBP & pushed to 7705'. Circ. clean & attempted to press. test csg. w/no results. TIH w/bit to 7900' &						
TOH. Schlumberger ran USIT log fr. 7700' - 6300'. Removed BOP & installed wellhead. 7-11; RDPU, cleaned location, & shut in well						
pending recompletion. 8-20; MIRU Key Energy Svc. pulling unit. Removed wellhead & installed BOP. TIH w/5-1/2" RBP set at						
6992'. TIH w/pkr. set at 5702' & press. RBP to 1000 PSI. Held OK. Moved pkr. at intervals testing & located csg. leak fr. 5145' – 5643'. TOH w/RBP. TIH w/5-1/2" CIBP & set at 7700'. Halliburton Svc. squeezed 75 sks. Premium Plus cement into csg. leak. WOC.						
TIH w/4-3/4" bit & tagged TOC at 5441'. Halliburton Svc. squeezed 75 sks. Premium Plus cement into csg. leak fr. 5145' – 5441'.						
WOC. TIH w/4-3/4" bit, tagged TOC at 4863' & drld. out cement at 5722'. TIH w/5-1/2" RBP set at 5800' & attempted to press. test						
csg. w/no results. Isolated csg. leak fr. 5	202' - 5574'. Halliburte	on Svc. squee:	zed 50 sks. Pi	emium Plus ceme	ent into csg. leak fr. 5600'	-
5100'. TIH w/4-3/4" bit, tagged cement at 5065' & drld. out cement at 5597'. TIH w/ret. tool, circ. sand off RBP & TOH w/RBP at						
5800'. Schlumberger TIH w/4" csg. gun & perf. 5-1/2" csg. w/4 SPF fr. 6984'-6986'. Attempted to est. inj. rate into perfs. w/no success.						
CONTINUED ATTACHED.						
I hereby certify that the information about						
SIGNATURE My Silvery		ΓLE <u>Specia</u>	<u>list – Field Ad</u>		October 11, 2002	
Type or print name Roy L. Wheele	er, Jr.			Telephone No.	710-86/ 618	
(This space for State use)	05:50					
APPPROVED BY	ORIGINAL SI	CHED BY			DATE MAR	
Conditions of approval, if any:	OC FIELD RE	KIE-		1	OCT 2 8 2002	