NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico OFFICE OCC

MISCELLANEOUS REPORTS ON WELLS

^M 11:18

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

		Indicate Nature of R	eport by Checkin	g Belov	V		
	BEGINNING OPERATIONS	REPORT ON RES	SULT OF TEST UT-OFF	x	REPORT ON REPAIRING W	ELL	
EPORT ON F PLUGGIN	RESULT NG WELL	REPORT ON RECOPERATION	COMPLETION		REPORT ON (Other)		x
		(Da	January 26,	1955		Midland,	Texas
	g is a report on the work of						
¥	Company or Oper	(Lease)					
Brar	tly Drilling Comp		, Well No	3-25	in the 1/4	SE 1/4 of Se	c. 25
20 -5 , F	38-E, NMPM.,	D-K Abo	Pool,		Lea	•••••	County
he Dates of 1	this work were as folows:	1-18-55 thru 1-2	8-55	***************************************			
	alon as de alon contrata	(man mot) submitted as Fo	C 10º an				19
	ntion to do the work		im G-102 0h	(C	ross out incorrect word	S)	, 13
nd approval	of the proposed plan	(was not) obtained.					
	DETAIL	ED ACCOUNT OF WOR	K DONE AND I	RESULI	S OBTAINED		
	UNIT TORE & COM	1 depth of 7466.	s in pressu	re. D	rilled out on	t. to 7460	A 101-104
-18-55 -20-55 -21-55 -22-55 1-24-55 1-25-55 1-26-55 1-27-55 1-28-55	Tested csg. w/ Perf. csg. 7403 Swabbed dry. Treated perfs w approximately 1 Set Baker plug 6 Perf. 5940-7030 with show oil. Treated with 400 Treated with 20, Set Baker retain	-7458, 7358-7388 / 3000 gal reg. a /2 bbl. water w/ 2 7198 & dumped 8 and 7045-95. Wash 0 gal acid - swah 000 gal Geofrac - er @ 7041 and squ Dumped 5 gal Hyd	and 7264-736 cid. Swabbe scum of oil gals. Hydro ed w/ 750 g bed dry swabbed ba seezed perfs	o8, We ed bac per late (al. max ck. loc 7045.	ished perfs which load and the control of the contr	/ 750 gal : hen recover est Drinka: d salt wat water w/: . cement-3	mud acioned acioned acioned acioned acioned acioned acidness acidn
-20-55 -21-55 -22-55 -24-55 -25-55 -26-55 -27-55	Tested csg. w/ Perf. csg. 7403 Swabbed dry. Treated perfs w approximately 1 Set Baker plug 6 Perf. 6940-7030 with show oil. Treated with 400 Treated with 20, Set Baker retain final pressure.	-7458, 7358-7388 / 3000 gal reg. a /2 bbl. water w/ 7198 & dumped 8 and 7045-95. Wash 0 gal acid - swah 000 gal Geofrac - er @ 7041 and squ Dumped 5 gal Hyd	and 7264-736 cid. Swabbe scum of oil gals. Hydro ed w/ 750 g bed dry swabbed ba seezed perfs	o8. We de bace per l'aite cal musco ck los 7045.	ek load and the r. on top. To to acid. Tester ad - then salt -95 w/ 45 sxser. Continuin	/ 750 gal : hen recover est Drinka: d salt wat water w/: . cement-3	mud acid red rd er show of 500# ps
-20-55 -21-55 -22-55 -24-55 -25-55 -26-55 -27-55	Tested csg. w/ Perf. csg. 7403 Swabbed dry. Treated perfs w approximately 1 Set Baker plug 6 Perf. 5940-7030 with show oil. Treated with 400 Treated with 20, Set Baker retain final pressure. A. T. Sindel, (Name)	-7458, 7358-7388 / 3000 gal reg. a /2 bbl. water w/ 7198 & dumped 8 and 7045-95. Wash 0 gal acid - swah 000 gal Geofrac - er @ 7041 and squ Dumped 5 gal Hyd	cid. Swabbe scum of oil gals. Hydro ed w/ 750 gals. Hydro ed w/ 750 gals. Example of the best of the b	o8. We ded back per la mite cal much ck lost 7045. etain.	ck load and the charton top. To to acid. Tester ad - then salt -95 w/ 45 sxs er. Continuin my of Texas	/ 750 gal nen recoverest Drinkard salt water w/ cement-3 g to test. Div.	mud acidered rd er show of 500# ps
-20-55 -21-55 -22-55 -24-55 -25-55 -26-55 -28-55	Tested csg. w/ Perf. csg. 7403 Swabbed dry. Treated perfs w approximately 1 Set Baker plug 6 Perf. 6940-7030 with show oil. Treated with 400 Treated with 20, Set Baker retain final pressure. A. T. Sindel, (Name)	-7458, 7352-7388 / 3000 gal reg. a /2 bbl. water w/ / 7198 å dumped 8 and 7045-95. Wash 00 gal acid - swah 000 gal Geofrac - er @ 7041 and squ Dumped 5 gal Hyd Jr. Wi	cid. Swabbe scum of oil gals. Hydro ed w/ 750 gals. Hydro ed w/ 750 gals. Example of the best of the b	o8. We ded back per limite of all must be call must be called must be calle	ck load and the control to	/ 750 gal nen recoverest Brinkard salt water w/. cement-3 g to test. Div.	red rd er show of 500# ps