N.M. OIL CONS. COMMISSION P.O. BOX 1980 HORRE NEW MEXICO 88740

Form 3160-5 (.1···-- 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Designation and Serial No. NMLCO 30132 - A
Do not use this form for proposals to dr	ill or to deepen or reentry to a different reservoir. R PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT &		7. If Unit or CA, Agreement Designation
1. Type of Well		UNIT A
X Oil Gas Uther		8. Well Name and No. TOM CLOSSON #5
2. Name of Operator		9. API Well No.
Southwest Royalties, Inc. 3. Address and Telephone No.		30-025-08805
P. O. Box 11390, Midland, Texas 79702 915 686-9927		10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		S. EUNICE SR QUEEN
Sec. 6, T-22S, R-36E Unit B 660' FNL & 1980' FEL		11. County or Parish, State LEA COUNTY, NM
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPOR	
TYPE OF SUBMISSION	TYPE OF ACTION	20 27
Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	X Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	U Other	(Note: Report results of multiple completion on Well
Describe Proposed or Completed Operations (Clearly state al	pertinent details, and give pertinent dates, including estimated date of starting	Completion or Recompletion Report and Log form) any proposed work. If well is directionally drilled,
give subsurface locations and measured and true vertic	al depths for all markers and zones pertinent to this work.)*	
The following is the proposed	procedure for squeezing casing leak:	
The following is the proposed 1. TIH w/CIBP, set @ 3500' &		E
1. TIH w/CIBP, set @ 3500' &		and pressures Bictate.
 TIH w/CIBP, set @ 3500' & Locate hole in 7" casing & Drill out squeeze and test 	cap w/35' of cement. S squeeze w/Class "C" cement as rates to 500# for 30 minutes. Chart record	d test a casing.
 TIH w/CIBP, set @ 3500' & Locate hole in 7" casing & Drill out squeeze and test 	cap w/35' of cement. & squeeze w/Class "C" cement as rates	d test a casing.
 TIH w/CIBP, set @ 3500' & Locate hole in 7" casing & Drill out squeeze and test *The BLM will be not 	cap w/35' of cement. S squeeze w/Class "C" cement as rates to 500# for 30 minutes. Chart record tified 48 hours prior to Rigging up and not plugging well : Well has Yates Potential	d test a casing. d prior to testing casing ential with Ature
1. TIH w/CIBP, set @ 3500' & 2. Locate hole in 7" casing & 3. Drill out squeeze and test *The BLM will be not *Justification for reperfs from 3276-346 Time frame for Reco	cap w/35' of cement. S squeeze w/Class "C" cement as rates to 500# for 30 minutes. Chart record tified 48 hours prior to Rigging up and not plugging well : Well has Yates Potential	d test se casing. d prior to testing casing the casing
 TIH w/CIBP, set @ 3500' & Locate hole in 7" casing & Drill out squeeze and test *The BLM will be not *Justification for reperfs from 3276-346 	cap w/35' of cement. So squeeze w/Class "C" cement as rates at to 500# for 30 minutes. Chart record tified 48 hours prior to Rigging up and not plugging well: Well has Yates Pote 56'.	d test se casing. d prior to testing casing the casing
1. TIH w/CIBP, set @ 3500' & 2. Locate hole in 7" casing & 3. Drill out squeeze and test *The BLM will be not *Justification for reperfs from 3276-346 Time frame for Reconstruct Thereby certify that the foregoing is true and correct	cap w/35' of cement. S squeeze w/Class "C" cement as rates to 500# for 30 minutes. Chart record tified 48 hours prior to Rigging up and not plugging well: Well has Yates Pote 66'. CAS: L.C. L. Third 30 DAY: Dempletion: When gas Prices Firm up to	d test Se casing. d prior to testing casing ential with Ature 1989. help economics
1. TIH w/CIBP, set @ 3500' & 2. Locate hole in 7" casing & 3. Drill out squeeze and test *The BLM will be not *Justification for r perfs from 3276-346 Time frame for Reco of workover. Thereby certify that the foregoing is true and correct Signed // Colon for the Nelson I	cap w/35' of cement. So squeeze w/Class "C" cement as rates at to 500# for 30 minutes. Chart record tified 48 hours prior to Rigging up and not plugging well: Well has Yates Pote 56'.	d test se casing. d prior to testing casing the casing
1. TIH w/CIBP, set @ 3500' & 2. Locate hole in 7" casing & 3. Drill out squeeze and test *The BLM will be not *Justification for reperfs from 3276-346 Time frame for Reconstruct Thereby certify that the foregoing is true and correct	cap w/35' of cement. S squeeze w/Class "C" cement as rates to 500# for 30 minutes. Chart record tified 48 hours prior to Rigging up and not plugging well: Well has Yates Pote 66'. CAS: L.C. L. Third 30 DAY: Dempletion: When gas Prices Firm up to	d test on casing. d prior to testing casing ential with ture the period of the state of the sta

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction