

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30 025-08969
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name A. L. Christmas B 17814
2. Name of Operator DALPORT OIL CORPORATION 5748	8. Well No. 1
3. Address of Operator 1401 Elm St. #3471, Dallas, Texas 75202	9. Pool name or Wildcat JALMAT GAS 74240
4. Well Location Unit Letter J : 1650 Feet From The SOUTH Line and 1650 Feet From The East Line Section 21 Township 22S Range 36E NMPM LEA County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3524

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was plugged and abandoned as follows: 10-23-91 thru 10-25-91

Set cast iron bridge plug at 2900 and cap with 35' cement
Load hole with mud
Set 35 sack plug 1300 to 1600
Cut off 5 1/2" casing at 350'
Set 55 sack plug 260 to 400 (8 5/8" casing shoe @ 310)
Set 10 sack plug at surface with dry hole marker
Clean & level location
Ready for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Harry L. Todd, Jr. TITLE Agent DATE 12/12/91

TYPE OR PRINT NAME Harry L. Todd, Jr. TELEPHONE NO. 214-748-7609

(This space for State Use)

APPROVED BY [Signature] TITLE OIL & GAS INSPECTOR DATE JAN 31 '92

CONDITIONS OF APPROVAL, IF ANY:

E