

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31644
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VB-134

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Lease Name or Unit Agreement Name Kiwi AKX State
2. Name of Operator YATES PETROLEUM CORPORATION	8. Well No. 5
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Pool name or Wildcat East Livingston Ridge Delaware
4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>East</u> Line Section <u>16</u> Township <u>22S</u> Range <u>32E</u> NMPM Lea County	

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

3728' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input checked="" type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input checked="" type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.  
Spudded 26" hole 3:00 PM 7-13-92. Set 40' of 20" conductor and cemented to surface. Notified NMOCDD, HOBBS, NM of spud. Resumed drilling 17 1/2" hole 2:30 PM 7-14-92. Ran 20 joints 13-3/8" 54.5# J-55 ST&C casing set 850'. Guide shoe set 850', insert float set 839'. Cmt'd w/500 sx PSL "C" w/2% CaCl2 (yield 1.76, wt 12.9). Tail in w/250 sx "C" w/2% CaCl2 (yield 1.32, wt 14.8). PD 3:13 PM 7-15-92. Bump plug to 500 psi, float held OK. Circulated 67 sacks. WOC. Drilled out 9:15 AM 7-16-92. WOC 18 hrs. Reduced hole to 11" and resumed drilling.  
Ran 112 joints 8-5/8" 32# HC-80 and J-55 casing set 4569'. Float shoe set 4569', float collar set 4533'. Cmt'd w/1300 sx PSL "C" w/10#/sx salt, 1/4#/sx Celloseal (yield 1.98, wt 12.8). Tail in w/200 sx "C" Neat (yield 1.32, wt 14.8). PD 12:45 AM 7-21-92. Bump plug to 3000 psi, float held OK. Circulated 325 sacks. WOC. Drilled out 9:45 PM 7-21-92. WOC 20 hrs. NU and tested to 1000 psi for 15 mins. Reduced hole to 7-7/8" and resumed drilling.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Juanita Goodlett TITLE Production Supervisor DATE 8-5-92  
TYPE OR PRINT NAME Juanita Goodlett TELEPHONE NO. 505/748-1471

(This space for State Use)

Orig. Signed by  
Paul Kautz  
Geologist

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE AUG 10 '92

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

AUG 10 1992

OCD HOBBS OFFICE