

NEW MEXICO STATE LAND OFF.
SANTA FE, NEW MEXICO

DEPARTMENT OF THE STATE GEOLOGIST
SANTA FE

NOTICE OF INTENTION TO ABANDON WELL

Notice must be given at least five days before work is to begin to the State Geologist or to the proper Oil and Gas Inspector. It is desirable that a representative of the Department of the State Geologist witness the plugging of wells being abandoned whenever possible. If changes in the proposed plan are considered advisable, a copy of this notice showing such changes will be returned to the sender. Submit this notice in duplicate.

Wink, Texas, N. Mex., **Apr. 5** 19**30**

Mr. **R. L. Halley**
Santa Fe, New Mexico.

Dear Sir:

You are hereby notified that it is our intention to abandon **State D** Well
No. **1** in **NW 1/4** of Sec. **3** of Sec. **31**, T. **21**, R. **33**
N. M. P. M., **Lea** Oil Field, **Lea** County.
We plan to commence work on **April 5**, 19**30**.

The reasons for wishing to abandon the well are as follows:

Hole Full Sulphur Water & T.D. 4046'

(Location of Well: 2310' from the North Line, 2310' from The West Line,
Block 6, Section 3, Tp.21, Tp. 33.

The present condition of the well is as follows:

10 " Casing Set @ 1834'
Top of Water Sand 4040' Hole Standing within 1500' Of top Sulphur Water.

The work which we propose to do in abandoning the well is as follows:

Bridge to 4030', Plug with Steel Cuttings, Lead Wool, and Drive Solid Lead Plug w/ Steel Mandrel.

Fill with Mud, Bridge and Drive Lead Plug at Top Lime (3780').
Fill with Mud, Bridge and Drive Lead Plug at Top Salt (1820') in 10" Casing. Fill Hole Full Mud and Cement Sellar.

Approved 4/10 1930

Sincerely yours,
CRANFILL REYNOLDS COMPANY

Except as follows:

By H. A. Reynolds Company or Operator.

Position **SUPT.**

Send communications regarding this well to

Name **H. A. Reynolds,**

Address **Box 685, Wink, Texas.**

R. L. Halley
State Geologist or Oil and Gas Inspector.