

UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
P.O. BOX 1890
ROSWELL, NEW MEXICO

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well gas well other

2. NAME OF OPERATOR
CONOCO INC.

3. ADDRESS OF OPERATOR
P. O. Box 460, Hobbs, N.M. 88240

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: **1980' FWL & 1980' FWL**
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

| | | |
|----------------------|--------------------------|-------------------------------------|
| TEST WATER SHUT-OFF | <input type="checkbox"/> | <input type="checkbox"/> |
| FRACTURE TREAT | <input type="checkbox"/> | <input type="checkbox"/> |
| SHOOT OR ACIDIZE | <input type="checkbox"/> | <input checked="" type="checkbox"/> |
| REPAIR WELL | <input type="checkbox"/> | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | <input type="checkbox"/> |
| MULTIPLE COMPLETE | <input type="checkbox"/> | <input type="checkbox"/> |
| CHANGE ZONES | <input type="checkbox"/> | <input type="checkbox"/> |
| ABANDON* | <input type="checkbox"/> | <input type="checkbox"/> |
| (other) | <input type="checkbox"/> | <input type="checkbox"/> |

5. LEASE
88240-032099(6)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME
NMFU

8. FARM OR LEASE NAME
Lockhart B-31

9. WELL NO.
6

10. FIELD OR WILDCAT NAME
Jalnet Yates Seven Rivers

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 31, T-215, R-36E

12. COUNTY OR PARISH
Lea

13. STATE
N.M.

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

RECEIVED
(NOTE: Report results of multiple completion or zone changes on Form 9-330.)
OCT 27 1982

**OIL & GAS
MINERALS MGMT. SERVICE
ROSWELL, NEW MEXICO**

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

MIRU 10-5-82. Tag @ 3547'. RIH w/ 4 1/2" csg scraper & 3 7/8" bit to 3920'. Set pkr @ 3706'. Acidize Seven Rivers Queen perf w/ 630 gals 15% HCL-NE-FE. Swab. Chemically inhibit w/ 200 bbls mixture and disp. w/ 150 BTFW. Rel. pkr. RIH w/ barrier. Knock out bridge @ 3920'. CO to 3889'. Set RBP @ 3520' & pkr @ 3223'. Load csg w/ TFW. Acidize Yates perf w/ 2500 gals HCL-NE-FE in equal stages mixed w/ salt. Swab. Rel pkr and RBP. Load JV @ 3893'. Run production equipment. Tested 10-24-82; 1980, 57 BW, & 33 MCF in 24 hrs.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED *D. E. Brinkman* TITLE Administrative Supervisor DATE 10-26-82

ACCEPTED FOR RECORD
(This space for Federal or State office use)
(ORIG. SGD.) **DAVID R. GLASS** TITLE _____ DATE _____

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY, _____

OCT 28 1982

**U.S. GEOLOGICAL SURVEY
ROSWELL, NEW MEXICO**
See Instructions on Reverse Side

RECEIVED
OCT 29 1982
HONORABLE
OFFICE