

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-04895
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-229
7. Lease Name or Unit Agreement Name	ARNOTT-RAMSAY (NCT-D)
8. Well No.	14
9. Pool name or Wildcat	EUMONT; YATES-7 RVRS QUEEN (PRO GAS)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER	2. Name of Operator Chevron U.S.A. Inc.
3. Address of Operator P.O. Box 1150, Midland, TX 79702	4. Well Location Unit Letter <u>H</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>33</u> Township <u>21S</u> Range <u>36E</u> NMPM LEA County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

SET CIRC @ 2845'; PPD CMT TO CIRC. SQZD 12 BBLS BELOW CIRC. SPOTTED BALANCED PLUG FROM CIRC TO 1560'. PERFD @ 1620' W/4 JHPF. SET CIRC @ 1560'. PPD 10 BBLS CMT IN FORM. SPOTTED PLUG FROM CIRC TO 360'. REVERSED OUT CMT. PERFD @ 358'. SET CIRC @ 300'; PPD CMT, CIRC UP 8-5/8" (NO CMT TO SURF BUT HAD GOOD CIRC). SPOTTED PLUG FROM CIRC @ 300' TO SURF. DUG OUT CELLAR, CUT OFF WH, INSTALLED DRY HOLE MARKER.

P&A'D 10/15/97

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. K. Ripley TITLE TECHNICAL ASSISTANT DATE 10/31/97
TYPE OR PRINT NAME J. K. RIPLEY

TELEPHONE NO. (915)687-7148

(This space for State Use)

APPROVED BY [Signature] TITLE [Signature] DATE 2-27-02
CONDITIONS OF APPROVAL, IF ANY:

TCAN

4