Submit 3 Copies to Appropriate District

Office	


State of New Mexico Energy, Minerals and Natural Resources

2. Name of Operator			320 <b>WFX-759</b>
Apache Corporation			320 <b>WFX-759</b> 9. Pool name or Wildcat
3. Address of Operator	Ste. 100. Houston, Texas 77056-44	100	Eunice N., Blinebry-Tubb-Drinkard
4. Well Location			***
Unit Letter		South Line and 1780	Feet From The West Line
Section	2 Township 21S Range	sther DF, RKB, RT, GR, etc.)	PM Lea County
	3476' GR		
II. NOT	Check Appa ICE OF INTENTION TO:	opriate Box to Indicate Nature of Notic SU	ce, Report, or Other Data JBSEQUENT REPORT OF:
Perform Remedia	Work Plug and Abandon	Remedial Wo	rk Altering Casing
Temporarily Abar		Commence D	orilling Operations Plug and Abandonment
Pull or Alter Casi	_ •	Casing Test a	and Cement Job
<u>_</u>	5	✓ Other	
Other		E out	Convert to Injection
12 Describe propose			and the second s
of starting any pro or recompletion.	l or completed operations. (Clearly state posed work). SEE RULE 1103. For Mu	e all pertinent details, and give peultiple Completions: Attach wellt	ortinent dates, including esumated date
of starting any pro	posed work). SEE RULE 1103. For Mu	oltiple Completions: Attach wellt  Nipple down wellhead, nipple	to be diagram of proposed completion  Ie up BOP. PU on the 10 pts - possible the part.
of starting any pro or recompletion.	MIRU. POH w/ pump & rods, LD. POH w/ 52 jts tbg - found body par RIH w/ OS, jars & bumper sub. La fishing tool & 4 1/2 jts tbg. RIH w thru top of fish @ 1790'. POH w/ f RIH w/ OS & torque each jt. Tag f w/ OS & latch fish. RIH w/ free po	Nipple down wellhead, nipple t 3' down on 53rd jt @ 1621'.  Attempt to 2' OS. Latch fish @ 1790'. RUree point tool. Attempted blin ish. Would not latch. POH woint tool. Found tbg free @ 55	to be diagram of proposed completion  Ie up BOP. PU on the 10 pts - possible the part.
of starting any proor recompletion. 5/30/00	MIRU. POH w/ pump & rods, LD. POH w/ 52 jts tbg - found body par RIH w/ OS, jars & bumper sub. La fishing tool & 4 1/2 jts tbg. RIH w thru top of fish @ 1790'. POH w/ f RIH w/ OS & torque each jt. Tag f w/ OS & latch fish. RIH w/ free po RIH w/ chemical cutter & cut tbg @ until AM. SDFN.	Nipple down wellhead, nipple t 3' down on 53rd jt @ 1621'.  Attempt to 1/20.  Attempt to 1/20.  Attempt to 1/20.  Attempt do 1/20.  Attempted bling ish. Would not latch. POH woint tool. Found tbg free @ 55@ 5540'. POH w/ chemical cu	le up BOP. PU on the 10 pts - possible the part. SDFN.  release TAC - twisted off tubing. POH w/ U WL. RIH w/ free point tool - could not get ad back off - backed off WS. POH w/ WS.  // BHA-found large pieces of the in OS. RIH  i57' (top of TAC). POH w/ free point tool.
of starting any proor recompletion.  5/30/00  5/31/00	MIRU. POH w/ pump & rods, LD. POH w/ 52 jts tbg - found body par RIH w/ OS, jars & bumper sub. La fishing tool & 4 1/2 jts tbg. RIH w thru top of fish @ 1790'. POH w/ f RIH w/ OS & torque each jt. Tag f w/ OS & latch fish. RIH w/ free po RIH w/ chemical cutter & cut tbg @ until AM. SDFN.  POH w/ 2-3/8" tbg and lay down. TAC - would not release. Jar on T. scraper to 5700'. POH w/ scraper.	Nipple down wellhead, nipple t 3' down on 53rd jt @ 1621'. Attempt to a fish @ 1621'. Attempt to a fish. Would not latch. POH whint tool. Found tbg free @ 55@ 5540'. POH w/ chemical current with the control of the co	le up BOP. PU on the 10 pts - possible the part. SDFN.  release TAC - twisted off tubing. POH w/ J WL. RIH w/ free point tool - could not get ad back off - backed off WS. POH w/ WS. J/ BHA-found large pieces of the in OS. RIH in 157' (top of TAC). POH w/ free point tool. tter. POH w/ OS - leave 2-3/8" the hanging
of starting any proor recompletion.  5/30/00  5/31/00  6/1/00	MIRU. POH w/ pump & rods, LD. POH w/ 52 jts tbg - found body par RIH w/ OS, jars & bumper sub. La fishing tool & 4 1/2 jts tbg. RIH w thru top of fish @ 1790'. POH w/ f RIH w/ OS & torque each jt. Tag f w/ OS & latch fish. RIH w/ free po RIH w/ chemical cutter & cut tbg ountil AM. SDFN.  POH w/ 2-3/8" tbg and lay down. TAC - would not release. Jar on T scraper to 5700'. POH w/ scraper.  Continued on other side	Nipple down wellhead, nipple t 3' down on 53rd jt @ 1621'.  Attempt to 1621'. Attempt to 1621'.  Attempt dollar in 1621'.	le up BOP. PU on the 10 pts - possible the part. SDFN.  release TAC - twisted off tubing. POH w/ J WL. RIH w/ free point tool - could not get ad back off - backed off WS. POH w/ WS.  // BHA-found large pieces of the in OS. RIH is 157' (top of TAC). POH w/ free point tool. tter. POH w/ OS - leave 2-3/8" the hanging  DC & WS. Latch fish. Attempt to release TAC w/ 10 jts 2-3/8" the RIH w/ casing
of starting any proor recompletion.  5/30/00  5/31/00  6/1/00	MIRU. POH w/ pump & rods, LD. POH w/ 52 jts tbg - found body par RIH w/ OS, jars & bumper sub. La fishing tool & 4 1/2 jts tbg. RIH w thru top of fish @ 1790'. POH w/ f RIH w/ OS & torque each jt. Tag f w/ OS & latch fish. RIH w/ free po RIH w/ chemical cutter & cut tbg ountil AM. SDFN.  POH w/ 2-3/8" tbg and lay down. TAC - would not release. Jar on T. scraper to 5700'. POH w/ scraper.  Continued on other side	Nipple down wellhead, nipple t 3' down on 53rd jt @ 1621'.  Attempt to 1621'. Attempt to 1621'.  Attempt dollar in 1621'.	le up BOP. PU on the 10 pts - possible the part. SDFN.  release TAC - twisted off tubing. POH w/ J WL. RIH w/ free point tool - could not get ad back off - backed off WS. POH w/ WS.  J BHA-found large pieces of the in OS. RIH in items of the point tool. Ster. POH w/ OS - leave 2-3/8" the hanging DC & WS. Latch fish. Attempt to release TAC w/ 10 jts 2-3/8" the RIH w/ casing
of starting any proor recompletion.  5/30/00  5/31/00  6/1/00	MIRU. POH w/ pump & rods, LD. POH w/ 52 jts tbg - found body par RIH w/ OS, jars & bumper sub. La fishing tool & 4 1/2 jts tbg. RIH w thru top of fish @ 1790'. POH w/ f RIH w/ OS & torque each jt. Tag f w/ OS & latch fish. RIH w/ free po RIH w/ chemical cutter & cut tbg ountil AM. SDFN.  POH w/ 2-3/8" tbg and lay down. TAC - would not release. Jar on T scraper to 5700'. POH w/ scraper.  Continued on other side	Nipple down wellhead, nipple t 3' down on 53rd jt @ 1621'.  Attempt to 1621'. Attempt to 1621'.  Attempt down wellhead, nipple to 1621'.  Attempt to 1621'. Attempt to 1621'.  Attempt down to 1621'. Attempt to 1621'.  Attempt down wellhead, nipple to 1621'.	le up BOP. PU on the 10 pts - possible the part. SDFN.  release TAC - twisted off tubing. POH w/ J WL. RIH w/ free point tool - could not get ad back off - backed off WS. POH w/ WS.  // BHA-found large pieces of the in OS. RIH is 157' (top of TAC). POH w/ free point tool. tter. POH w/ OS - leave 2-3/8" the hanging  DC & WS. Latch fish. Attempt to release TAC w/ 10 jts 2-3/8" the RIH w/ casing
of starting any proor recompletion.  5/30/00  5/31/00  6/1/00	MIRU. POH w/ pump & rods, LD. POH w/ 52 jts tbg - found body par RIH w/ OS, jars & bumper sub. La fishing tool & 4 1/2 jts tbg. RIH w thru top of fish @ 1790'. POH w/ f RIH w/ OS & torque each jt. Tag f w/ OS & latch fish. RIH w/ free po RIH w/ chemical cutter & cut tbg ountil AM. SDFN.  POH w/ 2-3/8" tbg and lay down. TAC - would not release. Jar on T scraper to 5700'. POH w/ scraper.  Continued on other side	Nipple down wellhead, nipple t 3' down on 53rd jt @ 1621'. Attempt to down tool. Attempted bling ish. Would not latch. POH woint tool. Found tog free @ 55@ 5540'. POH w/ chemical current with the control of the contr	le up BOP. PU on the 10 pts - possible the part. SDFN.  release TAC - twisted off tubing. POH w/ J WL. RIH w/ free point tool - could not get ad back off - backed off WS. POH w/ WS.  J BHA-found large pieces of the in OS. RIH in S57' (top of TAC). POH w/ free point tool. Itter. POH w/ OS - leave 2-3/8" the hanging  DC & WS. Latch fish. Attempt to release TAC w/ 10 jts 2-3/8" the RIH w/ casing  release TAC w/ 10 jts 2-3/8" the RIH w/ casing
of starting any proor recompletion.  5/30/00  5/31/00  6/1/00  Thereby certify that the inferrest signature  Type or print name	MIRU. POH w/ pump & rods, LD. POH w/ 52 jts tbg - found body par RIH w/ OS, jars & bumper sub. La fishing tool & 4 1/2 jts tbg. RIH w thru top of fish @ 1790'. POH w/ f RIH w/ OS & torque each jt. Tag f w/ OS & latch fish. RIH w/ free po RIH w/ chemical cutter & cut tbg ountil AM. SDFN.  POH w/ 2-3/8" tbg and lay down. TAC - would not release. Jar on T. scraper to 5700'. POH w/ scraper.  Continued on other side	Nipple down wellhead, nipple t 3' down on 53rd jt @ 1621'.  Attempt to 1621'. Attempt to 1621'.  Attempt down wellhead, nipple to 1621'.  Attempt to 1621'. Attempt to 1621'.  Attempt down to 1621'. Attempt to 1621'.  Attempt down wellhead, nipple to 1621'.	The core diagram of proposed completion  The up BOP. PU on the 10 pts - possible the part. SDFN.  The core diagram of proposed completion  The up BOP. PU on the 10 pts - possible the part. SDFN.  The core diagram of proposed completion  The up BOP. PU on the 10 pts - possible the part. SDFN.  The up BOP. PU on the 10 pts - possible the part. SDFN.  The up BOP. PU on the 10 pts - possible the part. SDFN.  The up BOP. PU on the 10 pts - possible the part. SDFN.  The up BOP. PU on the 10 pts - possible the part. SDFN.  The up BOP. PU on the 10 pts - possible the part. SDFN.  The up BOP. PU on the 10 pts - possible the part. SDFN.  The up BOP. PU on the 10 pts - possible the part. SDFN.  The up BOP. PU on the 10 pts - possible the part. SDFN.  The up BOP. PU on the 10 pts - possible the part. SDFN.  The up BOP. PU on the 10 pts - possible the part. SDFN.  The up BOP. PU on the 10 pts - possible the part. SDFN.  The up BOP. PU on the up BOP. SDFN.  The up BOP. PU on the up BOP. SDFN.  The up BOP. PU on the up BOP. SDFN.  The up BOP. PU on the up BOP. SDFN.  The up BOP. PU on the up BOP. SDFN.  The up BOP. PU on the up BOP. SDFN.  The up BOP

ICSN

Northeast Drinkard Unit # 320 API No. 30-025-06366 Convert to Injection C-103 Sundry continued

- 6/2/00 RU RBP & pkr, RIH. Set RBP @ 5690'. Set pkr @ 5679'. Pump 85 bbls 1% KCL down backside. Pressure test casing to 540# for 15 mins. OK. Release pkr and retrieve RBP. POH w/ tbg & tools. PU 4-3/4" bit & RIH to top of fill @ 5905'. Clean out to TD @ 5925'. POH w/ tbg & bit. SDFWE.
- 6/5/00 RIH w/ pkr, set pkr @ 5676'. Load backside to 500#. Acidize Blinebry open hole with 2000 gals 15% HCL Release pkr & circulate hole w/ KCL. POH w/ tbg & pkr. SDFN.
- 6/6/00 RIH w/ WS, SN & notch collar. Tag salt @ 5745'. Clean out to TD @ 5925'. POH & laydown WS. Unload 2-3/8" injection tbg. RIH w/ lok-set pkr & poly lined tbg. Left pkr swinging @ 5690'. SDFN.
- 6/7/00 Pump 100 bbls pkr fluid. Set pkr @ 5690'. Finish loading backside. Attempt MIT would not test. RU Wireline. RIH w/ 1-1/2" plug to test tbg. Stack out @ 2690'. POH w/ WL & plug. RIH w/ 1.48" gauge ring. Stack out @ 2690'. POH w/ gauge ring. RD Wireline. POH w/ pkr & tbg. Found 2 small holes in injection tbg @ 88th jt w/ poly liner collapsed. SDFN.
- 6/8/00 RIH w/ 2-3/8" inj tbg & pkr. Set pkr @ 5692'. Load backside w/ pkr fluid & attempt to work air cut of casing. Pressure backside to 500# lost 10# in 15 mins. Will allow air to work out of pkr fluid overnight & attempt final MIT in AM. Rig down. SDFN.
- 6/9/00 Run MIT. Test backside to 520# for 15 mins. tested OK. (See Attached) Prep to put on injection.
- 6/13/00 Hook well up to injection system. Put on injection.



State Lease-6 copies

Fee Lease-5 copies

State of New Mexico Energy, Minerals and Natural Resources

DISTRICT I 1625 N. French Dr., Hobbs	s, NM 88240								R	Form C-10 Revised March 25, 19
DISTRICT II							WELL API NO	),		tevised iviaien 23, 19
811 South First, Artesia, NI	M 88210		OIL CONSE			ON	30-0	025-06366		
DISTRICT III 1000 Rio Brazos Rd., Azteo	^ NM 97410			South Pache			5. Indicate Typ			
DISTRICT IV	c, 14141 0741U		Santa	Fe, NM 87	505		6. State Oil & O	STATE	FEE	<del></del>
2040 South Pacheco, Santa	Fe, NM 87505						o. State Off & C	Jas Lease 140.		
WE	LL COMPLI	ETION OF	RECOMPLETION	N REPORT	AND L	OG				
1a. Type of Well:	_						7. Lease Name	or Unit Agreemer	it Name	
b. Type of Completion:		AS WELL		OTHER		Injection		Northea	st Drinkar	d Unit
☐ New Well	■ Workover	De	epen 🔲 Plug Back	k 🔲 Diff.	. Resvr.	<b>✓</b> Other				
2. Name of Operator							8. Well No.		<del></del>	
Apache Corpora  3. Address of Operator	ation		<del></del>					320	<u> </u>	WFX-759
•	Blvd Ste 10	O Houston	n, Texas 77056-44	00 / 713 20/	5 6000		9. Pool name or		Tukk Dala	-1J
4. Well Location	51va., 5tc. 1c	70, 110 d3 t01	ii, 10Ad5 77030-44	00 / /13-250	3-0000		Eunice iv	., billiebry	-Tubb-Drii	nkard
Unit Lett	erW :	660	Feet From The	South	Line and	1780	Feet From The	We	est Line	
Section	on 2	Township	21S	Range	37E	NMPI	— м Lea	County		
10. Date Spudded	11. Date T.D. Rea	ched	12. Date Compl. (Ready to Pr		13. Eleva	tions (DF & RKB, RT, GF	· · ·	14. Elev. Casingl	nead	
15. Total Depth	16. Plug Bac	νTD	6/13/0 17. If Multiple Compl.			3476'	GR			
5925	10. Hug Bac	5925	Many Zones?	now		18. Intervals Drilled By	Rotary Tools		Cable Tools	
19. Producing Interval(s), o		op, Bottom, Name	<u> </u>			Diance By	<u> </u>	20. Was Directio	nal Survey Made	
Blinebry 5769 -		ion Interva	1							
21. Type Electric and Other	r Logs Run						22. Was Well C	Cored		
23.	<del></del>					<del></del>	_l			
			CASING RE	CORD (Re	port all	strings set in	well)			
CASING SIZE	WEIGHT		DEPTH SET	HOLE S	IZE	CEME	NTING RECO		AMC	OUNT PULLED
13-3/8 8-5/8	48		334	17-1/2		375 sx / Circu				
5-1/2	24# 8	2 3 <i>2</i> # 15.5#	3049 5769	7-7/8		2000 sx / TO				
<u>J-112</u>	1477 &	$1J.J\pi$		/-//		825 sx / TOC	@ 2080 (	151		
									<del>                                     </del>	
24. SIZE	I man I	LINER RE		1-	25.			TUBING REC	ORD	
SIZE	TOP	воттом	SACKS CEMENT	SCREEN	1	SIZE	DEP	TH SET	<del>                                      </del>	PACKER SET
	+ +			<u></u>	+	2-3/8			<del> </del>	5692
26. Perforation recor	d (interval size	and number)		<u></u>	27 AC	ID, SHOT, FRAC	PUDE CEME	NE COLTEC	TE ETC	
20. 10.01.01.00.10001	d (Interval, 5120,	una nameer)				EPTHINTERVAL	TOKE, CEIVIE		D KIND MATERI	IAL USED
<b>Blinebry</b> 5769 - 592:	5 Open Hole					5769 - 5925	Acidize w/ 2	2000 gals 15%		
					<u> </u>					
					<b>-</b>					<del></del>
					<u> </u>		-			<del></del>
						<del></del>				
28.	<del></del>			PRODUCT	TION				<del></del>	<del>-</del>
Date First Production	<del></del> .	7	Production Method	(Flowing, gas lift, p		e and type pump)		Well Stat	us (Prod. or Shut-	in)
6/13/00									Injecti	ng
Date of Test	Hours Tested		Choke Size Prod'n Test P		oil - Bbl.	Gas - MCF	Water - Bbl		Gas - O	il Ratio
Flow Tubing Press.	Casing Pressur	e Calculated		Gas - MO	OF	Water - Bbl.	<u> </u>		l Gravity - API - (e	Corr )
		Hour Rate		<u> </u>				O.	y zur*(t	
29. Disposition of Gas (Sola	d, used for fuel, vente	d, etc.)						Te	st Witnessed By	<u> </u>
30. List Attachments	<del></del>						<u>l</u>			<del> </del>
C-103 Sundry N	otice / MIT (	Chart #								
			is form is true and complete to	the best of my know	ledge and b	elief	<del></del> -	<del></del> -	<del></del>	
Signatur	. Kohna	Si Air	dorum	Printed Name Del	ora J. A	nderson	Tide Sr. E	Engineering	Technicia	an Date 7/28/00
							- DI. L	<sub>5</sub> cci iii	2 1 COMMON	MI Date 1/20/00
SWW /		U								

## **INSTRUCTIONS**

This form is to filed with the appropriate District Office of the Division Office not later than 20 days after the completion of any newly-drilled or deepened well. It shall be accompanied by one copy of all electrical and radio-activity logs run on the well and a summary of all special tests conducted, including drill stem tests. All depths reported shall be measured depths. In the case of directionally drilled wells, true vertical depths shall also reported. For multiple completions, items 25 through 29 shall be reported for each zone. The form is to be filed in quintuplicate except on state land, where six copies are required. See Rule 1105.

## INDICATE FORMATION TOPS IN CONFORMANCE WITH GEOGRAPHICAL SECTION OF STATE Southeastern New Mexico T. Anhy T. Canyon T. Ojo Alamo T. Penn. "B" T. Penn. "B"

T. Simpson T. Gallup T. McKee Base Greenhorn T. Dakota T. Ellenburger T. Dakota T. Gr. Wash T. Morrison T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. Chinle T. T. T. Permain T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES TO No. 3, from TO No. 4, from TMPORTANT WATER SANDS TO SEE TO	T. Strawn	nhy				~		E O!- 41		
T. Atoka T. Pictured Cliffs T. Miss T. Cliff House T. Devonian T. Menefee T. Silurian T. Point Lookout T. Mancos T. Mancos T. Simpson T. Gallup T. McKee Base Greenhorn T. Dakota T. Dakota T. Gr. Wash T. Morrison T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. Chinle T. T. Chinle T. T. Permain T. Permain T. Permain T. Penn "A" OIL OR GAS SANDS OR ZONES TO No. 3, from TMPORTANT WATER SANDS TO Seet	T. Atoka	lt				· —		=	414	
T. Miss T. Cliff House T. Devonian T. Menefee T. Silurian T. Point Lookout T. Montoya T. Mancos T. Simpson T. Gallup T. McKee Base Greenhom T. Ellenburger T. Dakota T. Gr. Wash T. Morrison T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. Chinle T. T. T. Chinle T. T. Permain T. Permain T. Permain T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES TO No. 3, from T. Morrison T. Penn "A"  OIL OR GAS SANDS T. Morrison T. Penn "A"  OIL OR GAS SANDS OR ZONES T. Morrison T. Morrison T. Morrison T. Morrison T. Penn "A"  OIL OR GAS SANDS OR ZONES T. Morrison T. Morrison T. Morrison T. Morrison T. Morrison T. Penn "A"  OIL OR GAS SANDS OR ZONES The more to make inflow and elevation to which water rose in hole. The more to feet Thickness in	T. Miss	-								
T. Devonian T. Menefee T. Silurian T. Point Lookout T. Mancos T. Mancos T. Mancos T. Gallup T. McKee Base Greenhom T. Delaware T. Delaware Sand T. Todilto T. Bone Springs T. T. Chinle T. T. T. Chinle T. T. T. T. Permain T. Permain T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES TO No. 3, from TO No. 4, from TMPORTANT WATER SANDS TO SEE SEE SANDS TO SEE S	T. Devonian T. Menefee T. Silurian T. Point Lookout T. Montoya T. Mancos T. Gallup T. McKee Base Greenhorn T. Ellenburger T. Dakota T. Gr. Wash T. Morrison T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. T. Chinle T. T. T. Permain T	<b>-</b>								
T. Silurian T. Point Lookout T. Mancos T. Mancos T. Gallup T. McKee Base Greenhorn T. Dakota T. Dakota T. Delaware Sand T. Permain T. T. T. T. T. T. T. Permain T. Permain T. Permain T. Permain T. Permain T. Permain T. Permain T. T	T. Silurian T. Montoya T. Mancos T. Montoya T. Mancos T. Gallup T. McKee Base Greenhorn T. Ellenburger T. Dakota T. Gr. Wash T. Morrison T. Delaware Sand T. T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. T. Chinle T. T. Permain T. Permain T. Permain T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES  No. 3, from IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet to feet LITHOLOGY RECORD (Attach additional sheet if necessa	-								
T. Montoya T. Mancos T. Simpson T. Gallup T. McKee Base Greenhorn T. Dakota T. Ellenburger T. Dakota T. Morrison T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. T. Chinle T. T. Permain T. Permain T. Penn "A" OIL OR GAS SANDS OR ZONES TO No. 3, from TO No. 4, from TMPORTANT WATER SANDS TO SEE STORM SEE S	T. Montoya T. Mancos T. Simpson T. Gallup T. McKee Base Greenhorn T. Ellenburger T. Dakota T. Gr. Wash T. Morrison T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. T. Chinle T. T. Permain T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES  to No. 3, from No. 4, from  IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet to feet LITHOLOGY RECORD (Attach additional sheet if necessa									
T. Simpson T. Gallup T. McKee Base Greenhorn T. Dakota T. Dakota T. Dellemburger T. Dakota T. Delaware Sand T. Morrison T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. T. T. T. T. Chinle T. T. T. T. T. Permain T. T. Permain T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES  TO No. 4, from  IMPORTANT WATER SANDS  TAR ON TAR OF THE SANDS  TO THE SANDS	T. Simpson	een					<del></del> ,		ıt <u></u>	
T. McKee Base Greenhom T. Ellenburger T. Dakota T. Gr. Wash T. Morrison T. Delaware Sand T. Toditto T. Bone Springs T. Entrada T. Rustler T. Wingate T. T. Chinle T. T. T. T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES  TO No. 3, from TMPORTANT WATER SANDS  TARIAN TO THE SANDS  TO	T. McKee Base Greenhom T. Ellenburger T. Dakota T. Gr. Wash T. Morrison T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. Chinle T. T. Permain T. Permain T. Penn "A" OIL OR GAS SANDS OR ZONES  No. 3, from No. 4, from IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet to feet LITHOLOGY RECORD (Attach additional sheet if necessal	yburg								
T. Ellenburger T. Dakota T. Gr. Wash T. Morrison T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. Chinle T. T. Permain T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES TO No. 3, from TO No. 4, from TMPORTANT WATER SANDS TO STANDS TO	T. Ellenburger T. Dakota T. Gr. Wash T. Morrison T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. Chinle T. T. T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES  to No. 3, from to No. 4, from  IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet to feet LITHOLOGY RECORD (Attach additional sheet if necessal	n Andre	es		•			=		
T. Gr. Wash T. Morrison T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. T. Chinle T. T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES TO No. 3, from To No. 4, from TMPORTANT WATER SANDS TO TAMPORTANT WATER SA	T. Gr. Wash T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. T. Chinle T. T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES  No. 3, from No. 4, from  IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet to feet LITHOLOGY RECORD (Attach additional sheet if necessal	orieta .			•					
T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. Chinle T. T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES To No. 3, from To No. 4, from  IMPORTANT WATER SANDS  Ta on rate of water inflow and elevation to which water rose in hole. To feet	T. Delaware Sand T. Todilto T. Bone Springs T. Entrada T. Rustler T. Wingate T. T. Chinle T. T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES  to No. 3, from No. 4, from  IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet to feet LITHOLOGY RECORD (Attach additional sheet if necessal	ddock.								
T. Bone Springs T. Entrada T. Rustler T. Wingate T. Chinle T. T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES TO No. 3, from TO No. 4, from TMPORTANT WATER SANDS TO SEE THE S	T. Bone Springs T. Rustler T. Wingate T. T. Chinle T. T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES  to No. 3, from  to No. 4, from  IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet to feet LITHOLOGY RECORD (Attach additional sheet if necessal									
T. Rustler T. Wingate T. Chinle T. T. Permain Bough C) T. T. Penn "A"  OIL OR GAS SANDS OR ZONES  To No. 3, from No. 4, from IMPORTANT WATER SANDS  It a on rate of water inflow and elevation to which water rose in hole. To feet To feet To feet Thickness in Thickness in	T. Rustler T. Wingate T. Chinle T. T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES  to No. 3, from  IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet to feet LITHOLOGY RECORD (Attach additional sheet if necessal	b .			•					
mp T. T. Chinle T. T. Permain  Bough C) T. T. Permain  OIL OR GAS SANDS OR ZONES  In to No. 3, from IMPORTANT WATER SANDS  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.  Ita on rate of water inflow and elevation to which water rose in hole.	T. T. Chinle T. T. Permain T. Permain T. Penn "A"  OIL OR GAS SANDS OR ZONES  to No. 3, from To No. 4, from  IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet to feet LITHOLOGY RECORD (Attach additional sheet if necessal	kard			•					
T. T. Permain  To DIL OR GAS SANDS OR ZONES  To Dil OR GAS SANDS O	T. T. Permain  T. Permain  T. Penn "A"  OIL OR GAS SANDS OR ZONES  to No. 3, from  No. 4, from  IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet  to feet  to feet  LITHOLOGY RECORD (Attach additional sheet if necessa		_			Rustler		-		
Bough C)  T. T. Penn "A"  OIL OR GAS SANDS OR ZONES  In to No. 3, from IMPORTANT WATER SANDS  Ita on rate of water inflow and elevation to which water rose in hole.  In to feet Ito feet Ito feet Ito feet Ito feet Ito feet ITHOLOGY RECORD (Attach additional sheet if necessary	OIL OR GAS SANDS OR ZONES  to No. 3, from  to No. 4, from  IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet  to feet  LITHOLOGY RECORD (Attach additional sheet if necessa	m	·							
OIL OR GAS SANDS OR ZONES  In to No. 3, from No. 4, from IMPORTANT WATER SANDS  It a on rate of water inflow and elevation to which water rose in hole.  In to feet to feet to feet to feet ILITHOLOGY RECORD (Attach additional sheet if necessary Thickness in feet to feet to feet the feet to feet	OIL OR GAS SANDS OR ZONES  to No. 3, from  No. 4, from  IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet  to feet  to feet  LITHOLOGY RECORD (Attach additional sheet if necessa									
to No. 3, from  IMPORTANT WATER SANDS  ta on rate of water inflow and elevation to which water rose in hole.  In to feet  It to feet  It to feet  LITHOLOGY RECORD (Attach additional sheet if necessary	to No. 3, from  to No. 4, from  IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet  to feet  to feet  LITHOLOGY RECORD (Attach additional sheet if necessa	Bo	ugh C)		. T.	OH OP (			TEC .	_
IMPORTANT WATER SANDS  ta on rate of water inflow and elevation to which water rose in hole.  In to feet  It THOLOGY RECORD (Attach additional sheet if necessary	to No. 4, from  IMPORTANT WATER SANDS  on rate of water inflow and elevation to which water rose in hole.  to feet  to feet  to feet  LITHOLOGY RECORD (Attach additional sheet if necessa									
IMPORTANT WATER SANDS  ta on rate of water inflow and elevation to which water rose in hole.  to	on rate of water inflow and elevation to which water rose in hole.  to						No. 3, from			•••••
ta on rate of water inflow and elevation to which water rose in hole.  to	on rate of water inflow and elevation to which water rose in hole.  to	m			to .		No. 4, Irom			
										·····
				,	LITH	OLOGY RECOR	D (Attach	additional sh	neet if necessary	)
		m		Thickness in	LITH				neet if necessary)	
				Thickness in	LITH				neet if necessary)  Thickness in Fee	
		n		Thickness in	LITH				neet if necessary)	
		n		Thickness in	LITH				neet if necessary)	
		om		Thickness in	LITH				neet if necessary)	
		m		Thickness in	LITH				neet if necessary	
		om		Thickness in	LITH				neet if necessary	
		m		Thickness in	LITH				neet if necessary)	
		rom		Thickness in	LITH				neet if necessary)	
		rom		Thickness in	LITH				neet if necessary)	
		om		Thickness in	LITH				neet if necessary)	
		rom		Thickness in	LITH				neet if necessary	
				Thickness in	LITH				neet if necessary	
		om		Thickness in	LITH				neet if necessary	
		rom		Thickness in	LITH				neet if necessary	
		m		Thickness in	LITH				neet if necessary	
		m		Thickness in	LITH				neet if necessary	