STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

	·	
40, 87 COPIES RECEIVED	. ł	
MOITUBIRTEID		
SANTA PE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION

P. O. BOX 2088

Form C-103 · Revised 10-1-73

SANTA FE, NEW MEXICO 87501		
rice	5a. Indicate Type of Lease	
U.S.G.S.	State Foo X	
OPERATOR	5. State Oil & Gas Lease No.	
<u></u>		
SUNDRY NOTICES AND REPORTS ON WELLS		
(00 NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT =" (FORM C-101) FOR SUCH PROPOSALS.)		
	7. Unit Agreement Name	
OIL GAS XX OTHER-		
2. Name of Operator	8. Farm or Lease Name	
SHELL OIL COMPANY	TAYLOR GLENN	
1. Address of Operator	9. Well No.	
P. O. BOX 991, HOUSTON, TX 77001	3	
4. Location of Well	10. Field and Pool, or Wildcat	
UNIT LETTER I . 3546 FEET FROM THE NORTH LINE AND 330 FEET FROM	BLINEBRY OIL AND GAS	
THE EAST LINE, SECTION 3 TOWNSHIP 21-S RANGE 37-E NAPPM		
THELINE, SECTION TOWNSHIP RANGE HMPM		
15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
3493' DF	LEA ()	
16. Check Appropriate Box To Indicate Nature of Notice, Report or Ot		
· · · · · · · · · · · · · · · · · · ·	T REPORT OF:	
308320021	TREFORT OF.	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING	
TEMPORARILY ABANDON COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING CASING TEST AND CEMENT JOB		
OTHER		
OTHER OPEN ADDITIONAL PAY AND ACIDIZE XX		
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including	e estimated date of starting any proposed	
work) SEE RULE 1103.	, seement and of contents any proposed	
1. Perforate 5-1/2" liner across Blinebry zone 5646' to 5773' (26 ho	loo)	
: Terrorate 3-1/2 Timer across bilineary zone 3040 to 5//3 (20 NO	ies).	
2. Acidize Blinebry perfs 5937' to 6045' w/2,000 gals 15% NEA.		
J parts to the wife gard tow them.		
3. Acidize Blinebry perfs 5806' to 5918' w/5,000 gals 15% NEA.		
4. Acidize Blinebry perfs 5646' to 5773' w/3,000 gals 15% NEA.		
5. Install production equipment and return well to production		
5. Install production equipment and return well to production.		
·		
	•	
10 The bound of the beautiful and the second of the second		
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
File (U.f.)	EEDOUADY 30 3000	
and date custings. A. J. FORE TITLE SUPERVISOR REG. & PERMITTING	PATE FEBRUARY 10, 1983	

ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR

PECELLED

FEB 1 4 1983

O.C.D. HOBBS OFFICE