

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN DUPLICATE*
(Other instructions on reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM-0025120

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Hawk B-10

9. WELL NO.

No. 4

10. FIELD AND POOL, OR WILDCAT

Wentz/Alco/Blin

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

10-21S-37E

12. COUNTY OR PARISH

Lea

13. STATE

NM

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Conoco Inc.

3. ADDRESS OF OPERATOR

P.O. Box 460 - Hobbs, New Mexico 88240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1980' FNL & 660' FRL - Unit Letter H

14. PERMIT NO.

30-025-06453

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. MIRR, if necessary kill well w/ 2% KCL TFW w/ 1 gal Adomall/1000 gals. POOH w/ rods & pump.

2. Run to pkr at 6680'. Tally out of hole.

3. RIH w/ CCK & CIBP setting 3' above pkr at 6680'. POOH.

4. RIH w/ pkr & set at 6100'. Pressure Abg to 500 psi. Release pkr & POOH.

5. Run producing equipment.

(This work is being performed in accordance w/ the requirements of Northeast Quinkard Unit prior to turning well over to Shell)

18. I hereby certify that the foregoing is true and correct

SIGNED *[Signature]*

TITLE Administrative Supervisor

DATE November 5, 1987

For space for Federal or State office use

APPROVED BY
COORDINATIONS OF APPROVAL, IF ANY:

TITLE

DATE 11-16-87

*See instructions on Reverse Side

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

BLM - Carlsbad (6) Hondo (2) Citico (1) Petro-Lewis (1) File

3A 11-16-87

Mike Colborn

ELEVATION: 3427' DF

ZERO: 12' AGL

1980' ENL & 660' FEL

SEC 10; T215-R37E

COMPLETION & WORKOVER HISTORY:

8-4-51: PERF (ELLENBURGER) 7584'-7690'

ACIDIZED W/1000 GAL

11-11-63: SET CIBP @ 7420'

PERF (ABO) 6721' TO 7366'


FRAC'D W/11,000 GAL W/3000# SAND

SET MODEL 'D' PACKER @ 6680'

PERF (BINEBRY) 5726' TO 5938'

FRAC'D W/22,000 GAL & 10,000# SAND

4-18-70: DOWN HOLE COMINGLES



MADE BY JLS

CHECKED BY

DATE 4-1-80

1 1

FILE

HAWK B-10 No 4

ABO & BINEBRY
NH

RECEIVED
NOV 17 1987
OCD
HOBBS OFFICE