

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form T-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State ☐	Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.

6. Name of Operator Shell Oil Company		7. Unit Agreement Name
8. Address of Operator P. O. Box 1509, Midland, Texas 79701		8. Farm or Lease Name Livingston
9. Location of Well UNIT LETTER <u>W</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM <u>East</u> <u>3</u> <u>21S</u> <u>37E</u> <u>NMPM.</u>		9. Well No. 2
10. Elevation (Show whether LL, RT, CR, etc.) 3433 DF		10. Field and Pool, or Wildcat Paddock
11. County Lea		

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐
PULL OR ALTER CASING ☐	OTHER <u>Test Paddock Zone</u> ☒

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐	ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOBS ☐	
OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.

1. Set CIBP at 5550' and cap with 35' of cement to abandon Elinebry.
2. Run GR-N and sonic logs. Perforate Paddock at intervals to be selected from log (5300-5425+).
3. Acidize and test zone.
4. Set BP at 5250' and perforate San Andres at intervals to be selected from log (5090-5180+).
5. Acidize and test zone.
6. Complete as warranted.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

N. W. Harrison

N. W. Harrison
Staff Prod. Engineer

2-26-74