	_	
O. OF COPIES RECEIVED		
DISTRIBUTION		T
NTAFE	T-	†
_E	1-	
3.G.S.	T	†
ND OFFICE	1	
ERATOR	†	

•	
DISTRIBUTION NTA FE NEW MEXICO OIL CONSERVATION COMMISS	Form C-103 Supersedes Old C-102 and C-103 Effective 1-1-65
ND OFFICE PERATOR	5a. Indicate Type of Lease State K Fee. 5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESE OIL K GAS WELL OTHER-	TRYOIR. 7. Unit Agreement Name
Texas Pacific Oil Company. Inc.	8. Farm or Lease Name
P. O. Box 1069, Hobbs, New Mexico 88240	State "A" A/c-1 9. Well No.
C. Hell	10. Field and Pool, or Wildcat
UNIT LETTER P . 660 FEET FROM THE South LINE AND 990 THE East LINE, SECTION 3 23-S 26-1	Langlie Mattix
THE LINE, SECTION 3 TOWNSHIP 23-S RANGE 36-1 15. Elevation (Show whether DF, RT, GR, etc.) 3460' DF	E NMPM.
Check Appropriate Box To Indicate Nature of Notice, Re	Lea Eport or Other Data UBSEQUENT REPORT OF:
PLUG AND ABANDON REMEDIAL WORK APPORARILY ABANDON COMMENCE DRILLING OPNS CHANGE PLANS CASING TEST AND CEMENT	ALTERING CASING PLUG AND ARRANGOMER
OTHEROTHER	
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent data work) SEE RULE 1603. 1. Move in and rig up. Install BOP. Pull rods, pump and to 2. Log 2500' to TD (3674'). 3. Set CIBP at 3630'. Perf higher Langlie Mattix as selected. Spot 250 gal 15% NE across perfs. Set packer 40' above up al. 15% NE. 5. Frac with 5000 pad, 20,000 gal. gelled 9# brine plus 30,000 Release packer - Run 2-3/8" tubing, pump and rods. 7. Place on production.	d from log. sper perf. Acidize with 1500
ereby certify that the information above is true and complete to the best of my knowledge and belief. **TITLE Area Superintendent**	
TIONS OF APPROVAL, IF ANS	BATE SCPCEMBEL II, 1970

.

RECEIVED

SEP 1 1 1970

OIL PONSEDURE ! C. SM.