

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

OIL CONSERVATION DIVISION

DISTRICT I
P.O. Box 1980, Hobbs NM 88241-1980

2040 Pacheco St.
Santa Fe, NM 87505

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO. 30-025-02428
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Lou Worthan
8. Well No. 12
9. Pool name or Wildcat Blinebry
10. Elevation (Show whether DF, RKB, RT, GR, etc.) GL: 3341 KB: 3356'

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL GAS WELL OTHER

2. Name of Operator
Marathon Oil Company

3. Address of Operator
P.O. Box 2409, Hobbs, NM 88240

4. Well Location
Unit Letter **H** : **1980** Feet From The **North** Line and **560** Feet From The **East** Line
Section **11** Township **22S** Range **37E** NMPM **Lea** County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: _____ <input type="checkbox"/>		OTHER: Sand Frac Blinebry <input checked="" type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/21 RU pulling unit. POOH w/pump & rods. ND wellhead. NU BOP. POOH w/tbg.
 7/22 RIH w/pkr, set at 5807'. Test CIBP at 6107', OK. Rel pkr, reset at 5277'.
 7/26 Frac w/97,518 gals CO2 foamed frac gel w/197,450# 16/30 sand. Flow back well.
 7/27 RIH tag sand at 5743'. Rel pkr, POOH. RIH w/tbg to 5733'. Clean out to 6107', PUH.
 8/1 RIH tag sand at 6072'. Run after frac log from 5000 to 5997'. POOH w/tbg. RIH w/2 3/8" tbg. ND BOP. NU wellhead.
 8/2 RIH w/pump & rods. RD pulling unit.

SN at 5787'
Btm of tbg 5827'

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kelly Cook TITLE Records Processor DATE 8/15/00
 TYPE OR PRINT NAME Kelly Cook TELEPHONE NO. 393-7106

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY:

