

NEW MEXICO OIL CONSERVATION COMMISSION Santa Fe, New Mexico MODES OFFICE OCC

MISCELLANEOUS NOTICES 1/1/2 23 PM 3:07
Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

		Indicate Nature of	Notice by Checking B	elow	
Notice of Intento Change Plan		Notice of Intention Temporarily Aband		Notice of Intention to Drill Deeper	
Notice of Inter to Plug Well	NTION	Notice of Intentic	ON	Notice of Intention to Set Liner	
Notice of Inter to Squeeze	NTION	Notice of Intention to Acidize	DN X	Notice of Intention ro Shoot (Nitro)	
Notice of Inter to Gun Perfora		Notice of Intention (Other)	PN	Notice of Intention (Other)	
OIL CONSERV SANTA FE, NE	VATION COMMISSIC	ON Ho t	obs, New Mexico	May 27, 1954	
Gentlemen:			(Flace)	(Date)	
Following is	s a Notice of Intention	to do certain work as descri	ibed below at the	F. J. Danglade	•••••
	Gulf Oil Co	orporation		Well Noin	M
QU 1/	(Company or O	perator)		Tubb Gas	(Unit)
(40-acre Sul	ibdivision)	, 1 	., R,NMPM	·· , ·······	Pool
Propose		FULL DETAILS OF PILOW INSTRUCTIONS IN and acidize in an	N THE RULES AND	REGULATIONS)	lows:
	reperforate 7" Straddle pres	LOW INSTRUCTIONS IN an and acidize in an acidize in acidize	n the RULES AND n effort to income 110' with h, 1/		v ith
2. 3. ApprovedExcept as follows	Perforate 7" Straddle prese 2000 gallons. Straddle new gallons.	e and acidize in an easing from 6030-65 ent perforations 6030-65 perforations 6030-65 ent.	n effort to inc. 110' with h, 1/ 140-6160'. Swal 6110'. Swab an	rease production as fol 2" Jet Heles per foot. b and test and acidise	with 3000
2. 3. ApprovedExcept as follows	Perforate 7" Straddle pres 2000 gallons. Straddle new gallons.	e and acidize in an easing from 6030-65 ent perforations 6030-65 perforations 6030-65 ent.	n effort to inc. 110' with h, 1/ 140-6160'. Swal 6110'. Swab an	rease production as fol 2* Jet Holes per foot. b and test and acidise d test and acidise with Gulf Oil Corporation Company or Operator Area Prod. Supt.	with 3000