

37. SUMMARY OF POROUS ZONES: (Show all important zones of porosity and contents thereof; cored intervals; and all drill-stem, tests, including depth interval tested, cushion used, time tool open, flowing and shut-in pressures, and recoveries):

| FORMATION     | TOP   | BOTTOM | DESCRIPTION, CONTENTS, ETC. | GEOLOGIC MARKERS |             |                  |
|---------------|-------|--------|-----------------------------|------------------|-------------|------------------|
|               |       |        |                             | NAME             | MEAS. DEPTH | TRUE VERT. DEPTH |
| Delaware      | 4974' | 5030'  | Fine grain, gray sand       | Anhydrite        | 1165'       | 1165'            |
|               |       |        |                             | Salado Salt      | 1310'       | 1310'            |
|               |       |        |                             | Base Lower Salt  | 4695'       | 4695'            |
|               |       |        |                             | Delaware Lime    | 4975'       | 4975'            |
| Delaware Sand |       | 5020'  |                             | 5020'            |             |                  |

38. GEOLOGIC MARKERS

| NAME            | TOP         |                  |
|-----------------|-------------|------------------|
|                 | MEAS. DEPTH | TRUE VERT. DEPTH |
| Anhydrite       | 1165'       | 1165'            |
| Salado Salt     | 1310'       | 1310'            |
| Base Lower Salt | 4695'       | 4695'            |
| Delaware Lime   | 4975'       | 4975'            |
| Delaware Sand   | 5020'       | 5020'            |