

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

Nov 18 8 01 AM '91

5. Lease Designation and Serial No.

NMLC034076

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Convest Energy Corporation

3. Address and Telephone No.

2401 Fountain View Dr, Suite 700, Houston, TX 77057

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

2310' FNL & 1650' FWL, Sec. 23, T23S, R36E

24

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Zattu Cushing #1

9. API Well No.

300250960600S1

10. Field and Pool, or Exploratory Area

Jalmat T-Y-SR

11. County or Parish, State

Lea County, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent
☐ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☒ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Notify BLM of plugging prior to starting work. (505) 393-3612
2. MI&RU rig. POH w/ production eqpt, LD everything except tbq.
3. GIH & set CIBP @ 3,005'. Spot 50' cmt on top.
4. * Perforate as necessary & place cement plugs:
2875-2775' inside & outside 6-5/8" csg, TAG PLUG.
1317-1217' inside & outside 6-5/8", 8-1/4" & 10" csgs. TAG PLUG.
Circulate or pump cement from 100' to surface in all casing annuli.
5. Cut off casings 4' below ground level, weld on 1/2" steel plate with marker.
Backfill & restore location.

* Fill WELLBORE BETWEEN ALL PLUGS WITH 9 PPG MUD.

14. I hereby certify that the foregoing is true and correct.

Signed

Robert J. Kelly

Title Sr. Petroleum Engineer

Date 11/11/91

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

11/24/91

DIAGRAMMATIC WELL SKETCH

PREPARED BY RE KELLEY DATE 11/8/91

PRESENT ☐ PROPOSED ☐

WELL NO. 1 LEASE ZATTU CUSHING FIELD JALMAT

