

Submit 3 Copies
 to Appropriate
 District Office
 District I
 P.O. Box 1980, Hobbs, NM 88240
 District II
 P.O. Drawer DD, Artesia, NM 88210
 District III
 1000 Rio Brazos Rd. Aztec, NM 87410

State of New Mexico
 Energy, Minerals and Natural Resources Department
OIL CONSERVATION DIVISION
 P.O. Box 2088
 Santa Fe, New Mexico 87504-2088

Form C-103
 Revised 1-1-89

WELL API NO.	30 - 025 - 10666
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit agreement Name	SKELLY PENROSE B UNIT
8. Well No.	43
9. Pool name or Wildcat	LANGLIE MATTIX 7 RVR Q-GB

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator	OXY USA INC.
3. Address of Operator	P.O. Box 50250 Midland, TX 79710
4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>NORTH</u> Line and <u>660</u> Feet From The <u>EAST</u> Line Section <u>8</u> Township <u>23 S</u> Range <u>37 E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3,323

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input checked="" type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER: <input type="checkbox"/>		SUBSEQUENT REPORT OF: REMEDIAL WORK <input checked="" type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: SET 4-1/2" LINER <input checked="" type="checkbox"/>	
---	--	--	--

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD - 3712' PBDT - 3630' PERFS - 3469' - 3614'
 MIRU PU 2/8/93, NDWH, NUBOP. POOH & FISH RODS, PUMP & TBG. RIH & TAG @ 2343. MILL, FISH & CLEAN OUT TO 3670'. RUN SN LOG, RIH & SET 4-1/2" LINER FROM SURF - 3660' & CEMENT W/330SX HOWCO LITE + 200SX CL C W/ 2% CACL2, CMT DID NOT CIRC, WOC. RIH & TAG @ 3608', DO TO 3630', RUN CBL - TOC-1432'. PERFORATE 3469-78, 3485-3500, 3504-10, 3513-21, 3529-33, 3538-53, 3583-92, 3603-3614', TOTAL 170 HOLES. ACIDIZE W/ 4000 GAL 15% NEFE HCL ACID. POOH W/ WS TBG & RIH W/ 2-3/8" TBG & SET @ 3599'. NDBOP, NUWH, RDPU 4/15/93 WO PUMP EQUIP. MIRU PU 5/6/93, NDWH NUBOP, POOH W/ TBG & PERF 2 HOLES @ 1200', EIR @ 3BPM@600#, M&P 264SX CL C W/ 2% CACL2 & CIRC CMT TO PIT, WOC. RIH & TAG CMT @ 1050', DO TO 1251'. M&P 35 SX CL C CMT W/ 2% CACL2, SQZ TO 1500#, WOC. RIH & TAG @ 873', DO TO 1286', FELL FREE, TEST CSG TO 500#-HELD OK. RIH W/ TBG & SET @ 3615', RIH W/ 2" X 1-1/2" X 16" BHD PUMP ON 66-RD STR, RDPU 5/13/93, START WELL PUMPING TO BATTERY @ 54"STR X 11 SPM.
 NMOCD POTENTIAL TEST 5/20/93 - 24HR 7-BO 53-BW GAS-TSTM

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE David Stewart TITLE Production Accountant DATE 06 09 93
 TYPE OR PRINT NAME David Stewart TELEPHONE NO. 915 685-5717

(This space for State Use)
 ORIGINAL SIGNED BY JERRY SEXTON
 DISTRICT SUPERVISOR
 APPROVED BY _____ TITLE _____ DATE JUN 15 1993
 CONDITIONS OF APPROVAL, IF ANY: