

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals

**SUBMIT IN TRIPLICATE**

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

KELTON OPERATING CORPORATION

3. Address and Telephone No.

POST OFFICE BOX 276, ANDREWS, TEXAS 79714-0276

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

330' FWL & 330' FEL ; Section 1, T-23-S, R-37-E

5. Lease Designation and Serial No.

NMNM2244

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Sarah B #3

9. API Well No.

30-025-32178

10. Field and Pool, or Exploratory Area

Wildcat San Andres

11. County or Parish, State

Lea, New Mexico

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☒ Notice of Intent

☐ Subsequent Report

☐ Final Abandonment Notice

TYPE OF ACTION

☐ Abandonment

☐ Recompletion

☒ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Spot 15% acid from 4578 - 4620'.
2. Perforate casing at 4596' - 4626' and swab and test for entry.
3. If no entry - acidize with 1000 gallons 15% acid and swab and test.

If no commercial production is found:

1. Set CIBP at 4580' and cap with 35' cement.
2. Spot acid and perforate at 4030' - 4050'. Swab and test interval for entry.
3. If no entry - acidize with 1000 gallons 15% acid. Swab and test.

Estimated start date: June 25, 2000

14. I hereby certify that the foregoing is true and correct

Signed C. Dale Kelton Title President

Date 6-1-00

(This space for Federal or State office use)

Approved by (ORIG. SCD.) JOE G. LARA

Title Petroleum Engineer

Date 6/28/2000

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side

