Form 9-331 (May 1963)		UBMIT IN TRIPLICATE.	Form approved. Budget Bureau No. 42-R1424.
(1211)	DEPARTME: OF THE INTERIOR "	Other instructions re- erse side)	5. LEASE DESIGNATION AND SERIAL NO.
	GEOLOGICAL SURVEY		LC-061935 062300
\$112	NDRY NOTICES AND REPORTS ON W	- T-1	6. IF INDIAN, ALLOTTER OR TRIBE NAME
		different reservoir.	NONE
1. OIL GAS			7. UNIT AGREEMENT NAME
WELL X WELL	OTHER		NONE
2. NAME OF OPERATOR	MDV LOO T		8. FARM OR LEASE NAME
	TEXACO Inc.		G. E. Jordan Federal NCT
3. ADDRESS OF OPERATOR P. O. Poy 728 Hobbs Nov. Marriage			9. WELL NO.
P. O. Box 728 - Hobbs, New Mexico			10
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface			10. FIELD AND POOL, OR WILDCAT
			Paduca Delaware
Well located 2130' from the South Line, and 2130' from the			11. SEC., T., R., M., OR BLK. AND SURVEY OR ARDA
East Line of Section 15, T-25-S, R-32-E, Lea County, N. M.			Sec. 15, T-25-S, R-32-E
4. PERMIT NO. 15. BLEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OR PARISH 13. STATE
Regular	3441 (D. F.)		Lea N. M.
•	Check Appropriate Box To Indicate Nature of Notice of Intention to:	SUBSEQU	ENT REPORT OF:
TEST WATER SHUT-		WATER SHUT-OFF	REPAIRING WELL
FRACTURE TREAT	 	RACTURE TREATMENT	ALTERING CASING ABANDONMENT
SHOOT OR ACIDIZE REPAIR WELL		I ABANDON MENT	
(Other)	CHARGE ABOUT	(Note: Report results	of multiple completion on Well tion Report and Log form.)
17. DESCRIBE PROPOSED	OR COMPLETED OPERATIONS (Clearly state all pertinent details, if well is directionally drilled, give subsurface locations and	. and give pertinent dates,	including estimated date of starting any

We propo	se to do the following work on subj	ect well:	
1. Tag	bottom with tubing, if bottom below	4708', skip iter	ns 2 & 3.
2. Usin	g pump truck, mud tank, tubing with otate, reverse circulate hole clean	to 1765 with wa	-joint, & tongs ater.
	00200, 10,0100 01100000 01010		
3. Swab	test well, if results unsuccessful	, proceed to iter	n 4.
4. Pull and	tubing, and frac with 3000 gallons flush with 100 bbls lease crude.	refined oil, 300	00 pounds of sand,
5. Swab	well, recover load oil, Test, and	place well on pro	oduction.

TITLE Assistant District

Superintenden

*See Instructions on Reverse SideISTRICT

TITLE

DATE Nov. 29, 1966

18. I hereby certify that the foregoing is true and correct

(This space for Federal or State office use)