

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Oil - Oil Dual Completion		5. LEASE DESIGNATION AND SERIAL NO. LC -032579 (e)	
2. NAME OF OPERATOR National Coop. Refinery Assoc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 2215 Wilco Bldg., Midland, Texas 79701		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface SW/4 NW/4 - Section 1, T-25-S, R-37-E 1730' FNL, 330' FWL of Section		8. FARM OR LEASE NAME Westates Federal	
14. PERMIT NO.		9. WELL NO. 5	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3140' DF		10. FIELD AND/POOL, OR WILDCAT Justis Tubb Drinkard Justis Blinebry	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 1, T-25-S, R-37-E	
		12. COUNTY OR PARISH Lea	13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF	<input type="checkbox"/>	PULL OR ALTER CASING	<input type="checkbox"/>
FRACTURE TREAT	<input checked="" type="checkbox"/>	MULTIPLE COMPLETE	<input type="checkbox"/>
SHOOT OR ACIDIZE	<input type="checkbox"/>	ABANDON*	<input checked="" type="checkbox"/>
REPAIR WELL	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
(Other)		Perforate	<input checked="" type="checkbox"/>

SUBSEQUENT REPORT OF:

WATER SHUT-OFF	<input type="checkbox"/>	REPAIRING WELL	<input type="checkbox"/>
FRACTURE TREATMENT	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
SHOOTING OR ACIDIZING	<input type="checkbox"/>	ABANDONMENT*	<input type="checkbox"/>
(Other)			

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Westates Federal No. 5 is dually completed in the Drinkard (5958'-6020' Intermittent) and (Blinebry 5270'-5502' Intermittent). The Drinkard is temporarily abandoned since it has reached its economic limit, and the Blinebry produces about 1.5 BO and 30 MCF per day.

The proposed workover is as follows:

1. Abandon Drinkard by setting a CI bridge plug at approximately 5900' with 10' cement on top of plug.
2. Plug off present Blinebry perfs 5270'-5502' by setting a CI bridge plug at approximately 5250' with 10' cement on top of plug.
3. Perforate Blinebry 5058', 5072', 5076', 5078', 5085', 5090', 5106', 5128', 5147', 5173', 5175', 5177', 5190', 5192', 5200', 5205', 5209', 5213', 5217', 5219', 5222', (21 holes).
4. Acidize with 2000 gals. and frac with 40,000 gals gelled brine and 60,000# sand.
5. Place well on production as single completion in Blinebry.

18. I hereby certify that the foregoing is true and correct

SIGNED B. J. KinserTITLE Dist. Prod. Supt.DATE 7-12-73

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____