

HALLIBURTON DIVISION LABORATORY  
HALLIBURTON COMPANY  
MIDLAND DIVISION

LABORATORY WATER ANALYSIS

No. W1-153-71

To Texas Pacific Oil Company, Inc.

Date 3/18/71

Box 4067

Midland, Texas 79701

Attn: Mr. Omar Roberts

This report is the property of Halliburton Company and neither it nor any part thereof nor a copy thereof is to be published or disclosed without first securing the express written approval of laboratory management; it may however, be used in the course of regular business operations by any person or concern and employees thereof receiving such report from Halliburton Company.

Submitted by E. England

Date Rec. 3/15/71

Well No. Wimberly # 3

Depth \_\_\_\_\_

Formation Tubbs Drinkard

County Lea

Field \_\_\_\_\_

East Jal

Source Battery Tank

Drinkard

Resistivity ..... .082 @ 74 F

Specific Gravity ..... 1.090

pH ..... 6.3

Calcium (Ca) ..... 6,800

\*MPL

Magnesium (Mg) ..... 2,460

Chlorides (Cl) ..... 81,000

Sulfates (SO<sub>4</sub>) ..... 2,300

Bicarbonates (HCO<sub>3</sub>) ..... 305

Soluble Iron (Fe) ..... Nil

Remarks:

\*Milligrams per liter

Respectfully submitted,

Analyst: Robert Lansford

cc:

HALLIBURTON COMPANY

By Robert Lansford

DIVISION CHEMIST

NOTICE

This report is limited to the described sample tested. Any user of this report agrees that Halliburton shall not be liable for any loss or damage, whether it be to act or omission, resulting from such report or its use.