

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State Fee

5. State Oil & Gas Lease No.
NMJ-581

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Plug and Abandon	7. Unit Agreement Name
2. Name of Operator TEXAS PACIFIC OIL COMPANY	8. Farm or Lease Name Gutman "D"
3. Address of Operator P. O. Box 1069 - Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER I , 1830 FEET FROM THE South END AND 660 FEET FROM THE East LINE, SECTION 29 TOWNSHIP 25-S RANGE 37-E N.M.P.M.	10. Field and Pool, or Wildcat Crosby Devonian
15. Elevation. (Show whether DB , KL , GR , or ...) 3011' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK

TEMPORARILY ABANDON

PULL OR ALTER CASING

OTHER

PLUG AND ABANDON

CHANGE PLANS

REMEDIAL WORK

COMMENCE DRILLING OPNS.

CASING TEST AND CEMENT JOB

OTHER

ALTERING CASING

PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Pull tubing and packer.
2. Set C.I. Bridge Plug at 8400' (Perfs. 8468-8483') on wire line w/2 sks. cement on top of plug.
3. Run tubing and displace well fluids with drilling mud (8400' to surface).
4. Pull tubing and shoot off 7' casing at 5045' (Cement top 5045' by temperature survey).
5. Lay down 7" casing.
6. Run tubing and spot 25 sks. cement at cut off (Approx. 5045').
7. Spot 25 sks. cement at bottom 9-5/8" pipe at 3613'.
8. Remove well head equipment.
9. Spot 10 sks. at surface and install dry hole marker.
10. Clean location and fill cellar.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

Original Signature of

SIGNED Sheldon Ward TITLE Area Superintendent DATE 4-22-68

APPROVED BY [Signature] DATE _____

CONDITIONS OF APPROVAL, IF ANY: