

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions
reverse side)

Form approved.
Budget Bureau No. 42-R1424

LEASE DESIGNATION AND SERIAL NO.

02875

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Anderson

9. WELL NO.

3

10. FIELD AND POOL, OR WILDCAT

Allison Penn

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 29-T8S-R37E

12. COUNTY OR PARISH

Roosevelt

13. STATE

N.M.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL GAS WELL OTHER

2. NAME OF OPERATOR
Eugene E. Nearburg

3. ADDRESS OF OPERATOR
4219 Sigma Road, Dallas, Texas 75240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)
At surface

1980' FSL & 1980' F EL of Sec. 29
Unit Letter J.

AUG 16 1971
U.S. GEOLOGICAL SURVEY
HOBBBS, NEW MEXICO

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4041' GR.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF
FRACTURE TREAT
SHOOT OR ACIDIZE
REPAIR WELL
(Other)
PULL OR ALTER CASING
MULTIPLE COMPLETE
ABANDON*
CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF
FRACTURE TREATMENT
SHOOTING OR ACIDIZING
(Other)
REPAIRING WELL
ALTERING CASING
ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We plan to plug well as follows:

Tubing is stuck
Spot 25SX plug thru tubing over perfs.
Load hole
Tubing stuck at 3975' cut tubing at 3954' and pull.
cut 4 1/2" casing at 3913' and pull
Spot 25 SX plug at 4 1/2 stub. (3913')
Spot 10 SX plug at surface set dry hole marker.
Clean up location
This was approved by Joe Ramey.

18. I hereby certify that the foregoing is true and correct

SIGNED Eddy J. Schick TITLE Production Supt.

DATE 8-11-71

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:

AUG 13 1971

*See Instructions on Reverse Side

RECEIVED

SEP 21 1971

OIL CONSERVATION COMM.
HOBBS, N. M.