

original

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
March 4, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-02190
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-155-1
7. Lease Name or Unit Agreement Name West Vacuum Unit
8. Well Number 33
9. OGRID Number
10. Pool name or Wildcat Vacuum Grayburg San Andres

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well  Gas Well  Other

2. Name of Operator  
Chevron USA Inc

3. Address of Operator  
15 Smith Rd, Midland, TX 79705

4. Well Location  
Unit Letter P : <sup>660</sup>~~1980~~ feet from the North line and <sup>660</sup>~~1980~~ feet from the West line  
Section 33 Township 17-S Range 34-E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

**Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)**

Pit Location: UL P Sect 33 Twp 17S Rng 34E Pit type Steel Depth to Groundwater 87 Distance from nearest fresh water well Over 1000'  
Distance from nearest surface water \_\_\_\_\_ Below-grade Tank Location UL \_\_\_\_\_ Sect \_\_\_\_\_ Twp \_\_\_\_\_ Rng \_\_\_\_\_ ;  
1980 feet from the North line and 1980 feet from the West line (Steel Tank)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

- PERFORM REMEDIAL WORK  PLUG AND ABANDON
- TEMPORARILY ABANDON  CHANGE PLANS
- PULL OR ALTER CASING  MULTIPLE COMPLETION
- OTHER:

- REMEDIAL WORK  ALTERING CASING
- COMMENCE DRILLING OPNS.  PLUG AND ABANDONMENT
- CASING TEST AND CEMENT JOB
- OTHER:

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- Notify OCD 24 hrs prior to MI and RU.
- RIH Tag CIBP at +-4135, spot 25sx, plug from 4135-3950 (San Andres).
- Displace hole w/MLF, 9.5# Brine w/~~25#~~ gel P/BBL. 12.5
- Perf 4 holes at 2800, sqz 50sx, plug from 2800-2600 (Yates, B-Salt).
- Cut 5 1/2" csg at 950, L/D csg.
- Spot 75sx, plug from 1000-860 (Stub, 8 5/8 Shoe) WOC Tag.
- Spot 80sx, plug from 300-Surf (Surf).

8. Install dry hole marker.

**THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS.**

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit  or an (attached) alternative OCD-approved plan .

SIGNATURE [Signature] TITLE Consultant DATE 11-2-04

Type or print name Jeremy Bagley E-mail address: \_\_\_\_\_ Telephone No. 432-561-8600

(This space for State use)

APPROVED BY [Signature] TITLE OC FIELD REPRESENTATIVE W/STAFF MANAGER DATE NOV 08 2004  
Conditions of approval, if any: \_\_\_\_\_

