

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

By JKeyes at 9:58 am, Jun 27, 2016

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	OCCIDENTAL PERMIAN LTD.	Contact	TONY AGUILAR
Address	1017 W. Stanolind Road, Hobbs	Telephone No.	575-397-8251
Facility Name	NHU 32-241	Facility Type	OIL AND GAS PRODUCTION FACILITY
Surface Owner	Occidental Permian LTD.	Mineral Owner	HOBBS (G-SA)
		API No.	30-025-07533

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	32	18-S	38-E					Lea

Latitude_32.69917_ Longitude_103.17121_

NATURE OF RELEASE

Type of Release	NA	Volume of Release	NA	Volume Recovered	0
Source of Release	NA	Date and Hour of Occurrence	6-13-16 @ 5:45PM	Date and Hour of Discovery	6-13-16 @ 5:45PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	MAXEY BROWN		
By Whom?	TONY AGUILAR	Date and Hour	6-13-16 @ 6:56PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	N/A		

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Cause: BIRD LANDED ON POWER POLE LOCATED JUST OUTSIDE THE FENCE AT THE NHUNIB CAUSING A PHASE TO GROUND ARC CAUSING AN ARC AT NHU32-241 THEREFORE CAUSING A SMALL GRASS FIRE. COVERED AN AREA 75'X 110'. NO DANGER TO PUBLIC.



Remedial Action Taken:

HOBBS FIRE DEPT/POLICE WAS CALLED OUT AND HFD WAS ABLE TO EXTINGUISH FIRE IMMEDIATELY. REPAIRS WERE MADE TO BOTH POWER POLES. AND POWER WAS RESTORED.

Describe Area Affected and Cleanup Action Taken.*

75'X110' PASTURE LAND WAS AFFECTED, THERE IS NO CLEAN UP REQUIRED.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: TONY AGUILAR	Approved by Environmental Specialist: 		
Title: HES SPECIALIST	Approval Date: 06/27/2016	Expiration Date: ///	
E-mail Address: RAYMOND_AGUILAR@OXY.COM	Conditions of Approval: ///		Attached <input type="checkbox"/> nJXX1617934304
Date: 6-20-16	Phone: 575-397-8251		

* Attach Additional Sheets If Necessary