<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141

Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action

						OPERATOR ⊠ Initial Report ⊠ Final Report				
1 0 50 1 0							Contact Randall Gladden, Production Foreman			
•						Telephone No. 575-513-9463				
Facility Name Thistle Unit #43H							Facility Type Oil			
Surface Owner State Mineral Owner						State API No 30-025-40898				
LOCATION OF RELEASE										
Unit Letter	Section	Township	Range	Feet from the		South Line Feet from the East/West Line County				
M	33	23S	33E	200	S	South 500 West Lea			Lea	
Latitude: 32.2545166 Longitude: -103.5841522										
NATURE OF RELEASE										
Type of Release Oil & produced water							Volume of Release 1 BBL Oil & Volume Recovered 0 BB 1 BBL produced water			
Source of Release Stuffing box						Date and Hour of Occurrence Date and			and Hour of Discovery 2016 @ 11:00am	
Was Immediate Notice Given?						If YES, To Whom?				
							OCD-Jamie Keyes Date and Hour			
						OCD - 7/18/2016 @ 2:16pm				
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse N/A				
If a Watercourse was Impacted, Describe Fully.* N/A										
Describe Cause of Problem and Remedial Action Taken.* 1 BBL oil and 1 BBL produced water was released from the stuffing box due to the seal on the rubber packing blowing out. The rams on the well head were closed to prevent further release. The packing was replaced and the well has been returned to operation.										
Describe Area Affected and Cleanup Action Taken.* 1 BBL of oil and 1 BBL produced water was released from the stuffing box on top of the well head due to the seal on the rubber packing blowing out. Due to high winds some of oil and produced water was blown into the pasture. The area affected was on the Northern portion of the Pad next to the pasture with some fine mist reaching approximately 461' feet into the pasture. The total affected area on and off pad was 75' wide by 671' long. Vacuum truck was unable to recover any of the released oil and produced water. Environmental agency will be contacted for remediation.										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.										
Signature: Sarah Gallegos-Troublefield							OIL CONSERVATION DIVISION			
Printed Name: Sarah Gallegos-Troublefield						Approved by Environmental Specialist:				
Title: Field Admin Support						Approval Dat	e:	Expiration Date:		
E-mail Address: Sarah.Gallegos-Troublefield@dvn.com						Conditions of Approval:			Attached	

Phone: 575.748.1864

Date:7/19/2016

^{*} Attach Additional Sheets If Necessary

Thistle Unit 43H 2 BBLS Oil & PW



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere Prepared by: Sarah Map is current கூர்ஜக புழைக்குield

Ż

Miles 0.00 0.01 0.02 1:889



