<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720 District II

Bill S. First St., Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720
District III
1000 Rio Brazos Road, Aztec, NM 87410
Phone: (505) 334-6178 Fax: (505) 334-6170

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3460 Fax: (505) 476-3462

State of New Mexico

Form C-101 Revised July 18, 2013

Energy Minerals and Natural Resources

Oil Conservation Division OCD - HOBB S AMENDED REPORT

1220 South St. Francis Dr.

07/26/2016 RECEIVED

Santa Fe, NM 87505

APPLI	CATIO	N FOR	PEI	RMIT T	O DR	ILL,	RE-EN	NTER	, DI	EEPEN	, PL	UGBAC	CK, (OR AD	DAZ	ONE	
1. Operator Name and Address										~	/	OGRID Number 873					
Apache Corporation: 303 Veterans Airpark Lane, Suite 1000 Midla									nd, TX 79705				30-025-34163 API Number				
309138 J H Williams					³ Property Name						13	002 ° Well No.					
						7. St	ırface Lo	ocation									
UL - Lot	JL - Lot Section Township Range 34 19S 37E		Range Lot Idn			Feet from 470		N/S Line South		Feet From 990			E/W Line East		County		
	04	100	JOIL		8 P	ronos	ed Botton				000		Las		Lea		
UL - Lot	- Lot Section Township Range		Range	Lot Idn		Feet from		N/S Line		F	Feet From		E/W Line		County		
Р	34 198		37E				470		South		990		East		Lea		
						9. Pc	ool Infor	mation									
Eumont; Yat						Pool Code 22800											
					Ad	dition	al Well I	Informa	ation								
= P Worl	к Туре	0	12 1	Well Type	R 13. Cable/R			Rotary	tary		14. Lease Type		15. Ground Level Elevatio 3569			Elevation	
16 Multiple				posed Depth	18 Forwar			ntion 7D C			19. Contractor		²⁰ Spud Date			te	
No 7,000' Tubb / Drift Depth to Ground water Distance from nearest fresh												Distance to nearest			6/1997		
Deptil to Grou	na water			Distai	ice nom	nemest	iresii water	wen				Distance	o to nea	rest surrace	water		
✓ We will be	using a c	losed-loop	syste	n in lieu of	lined p	its											
				21.	Propos	ed Ca	sing and	Cemer	ıt Pı	ogram							
Туре	Type Hole Size		Casing Size Casing			sing We	ng Weight/ft			g Depth		Sacks of	Cemer	ment Estimated TOC			
Surface	urface 12-1/4"		9-5/8"		36#			1241'			600 sxs		sxs	(S		65'	
Intermediat	ermediate 8-3/4"		7"		23#			4		4030'		400 sx		sxs		62'	
Production 6-1/8		1/8"	4-1/2"		10.5#		#	7000'			265 sxs			(S			
							ogram: A	Additio	nal (Comment	s						
Isolate open	perfs (D	rinkard, 1	ubb)	and re-cor	nplete	in Eun	nont										
				^{22.}]	Propos	ed Blo	wout Pr	eventio	n Pr	ogram							
		Working Pressure				Test Pressu			sure	sure		Manufacturer					
7																	
^{23.} I hereby certify that the information given above is true and complete to the best of my knowledge and belief.								OIL CONSERVATION DIVISION									
I further cert 19.15.14.9 (B)	ify that I I	nave compl	ied wit	h 19.15.14.9	(A) NM	IAC 🗌	and/or	Approv	ed B	<i>r</i> :		-/					
Signature:	Isabe	11						0.000			12	auk					
Printed name:	/	10.0	201					Title:		Petrole	um E	ngineer					
Title: Regulatory Analyst									red Da	ate: 07/2	6/20	16	Expirati	on Date: ()7/26/20)18	
E-mail Addres	ss: Isabel.	Hudson@)apac	hecorp.co	m							1					
Date: 07/25/2016 Phone: (432) 818-1142									Conditions of Approval Attached								





July 21, 2016

Williams JH # 2 API # 30-025-34163 Lea County, NM

Production Casing: 4-1/2" 10.5# Set @ 7,000'

Producing Interval: 6,418-904'

Objective: Isolate open perfs (Drinkard, Tubb) and re-complete in Eumont

Procedure:

- 1. POOH with rods and tbg
- 2. Set CIBP @ 6,380' with 35' cmt
- 3. Fill up casing with 7% KCL water
- 4. Pressure test casing to 600 psi
- 5. RIH with a wireline re-entry guide, 1.875 X-nipple, 10' pup jt, 5K tension set packer and test tbg to 80%
- 6. Set top of packer @ 3,380'
- 7. Pressure up casing to 500 psi.
- 8. Swab well down to 2,000'
- 9. Perforate with 1-11/16" strip gun (4 spf 0° phasing, deep penetrating charges):
 - 3,442-51'
 - 3,472-76'
 - 3,480-94'
 - 3,500-08'
 - 3,512-22'
 - 3,538-42'
 - 3,560-64'
 - 3,583-96'
 - 3,600-05
 - 3,620-28'
 - 3,640-45
 - 3,652-62'
- 10. Rig up acid truck
- 11. Load tbg with acid and break down formation with acid. Use 7% KCl water to displace acid
- 12. Do not over displace water into the formation. Leave 2-3 bbls of acid in the tbg
- 13. Swab test well and determine if a rod pump is required
- 14. Return the well to production

Apache Corporation – J.H. Williams #2

Wellbore Diagram - Current

API: 30-025-34163

Date: 3/30/2016

Surface Location

K. Grisham

470' FSL & 990' FEL, Lot P Sec 34, T19S, R3

Lot P Sec 34, T19S, R37E, Lea County, NM

Surface Casing

9-5/8" 36# @ 1241' w/ 600 sxs to surface

TOC @ 3565'

Intermediate Casing 7" 23# J-55 @ 4030' w/ 400 sxs. TOC @ 2862'

7/12: Treat for paraffin. Acid frac Drinkard w/ 64,386 gals acid. Acidize Tubb w/ 2500 gals 15% HCl, drop 120 ball sealers, no ball action.

5/98: Perf Tubb @ 6418-6614 w/ 2 jspf (90 holes) Acidized w/ 10,000 gal 15 % NEFE w/ 136 mcf N2 8/12: Acidized w/ 2500 gallons 15% NEFE

11/97: Perf Drinkard @ 6812-6904 w/ 2 jspf (118 holes) Acidized w/ 5000 gal 15% HCL

8/12: Acid frac with 860 bbs 12# XL assist and 64,386 gal 15% Divert S acid system.

Production Casing 4-1/2" 10.5# J-55 @ 7000' w/ 265 sxs

KB=3579° Spud:10/26/97 Hole Size =12-1/4" Hole Size =8-3/4" Hole Size =6-1/8"

GL=3569'

PBTD = 6,950'MD = 7,000'