

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis  
Santa Fe, NM 87505

**RECEIVED**

By JKeyes at 9:25 am, Aug 17, 2016

**Release Notification and Corrective Action**

**OPERATOR**

☒ Initial Report

☒ Final Report

Name of Company: Chevron USA Inc.	Contact: Josepha DeLeon	
Address: 6301 Deauville, Midland, TX 79706	Telephone No.: 432-425-1528	
Facility Name: Central Vacuum Unit #201	Facility Type: Injection	
Surface Owner	Mineral Owner	API No.: 30-025-32806

**LOCATION OF RELEASE**

Unit Letter G	Section 06	Township 18S	Range 35E	Feet from the 1360	North/South Line North	Feet from the 1973	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	---------------

**Latitude** 32.7804985 **Longitude** -103.4948425

**NATURE OF RELEASE**

Type of Release: Injection CO2 Line rupture gas release	Volume of Release: 75 MCF	Volume Recovered: 0
Source of Release: Injection CO2 Line rupture	Date and Hour of Occurrence: 8/5/2016; 12:30 AM	Date and Hour of Discovery: 8/9/2016; 6:31 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD - Voice Message	
By Whom? Cullen Jones	Date and Hour: 8/9/2016 8:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
N/A



Describe Cause of Problem and Remedial Action Taken.\*

Rupture at connection between fiberglass piping. Pressure upstream of choke and line were equalized.

Describe Area Affected and Cleanup Action Taken.\*

Repaired CO2 line.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Josepha DeLeon		Approved by Environmental Specialist: 	
Title: HES Compliance Support - Environmental		Approval Date: 08/17/2016	Expiration Date: ///
E-mail Address: jdx@chevron.com		Conditions of Approval:  ///	Attached <input type="checkbox"/>  nJXK1623033848
Date: 8/16/2016 Phone: 432-425-1528			

\* Attach Additional Sheets If Necessary