

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC [OGRID] 229137	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077	
Facility Name: PYGMY 27 STATE #003H	Facility Type: Battery	
Surface Owner: Private	Mineral Owner: State	API No. 30-025-42068

LOCATION OF RELEASE

Unit Letter B	Section 27	Township 21S	Range 33E	Feet from the 190'	North/South Line North	Feet from the 1980'	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	---------------

Latitude 32.4565239 Longitude - 103.5581741

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 70 bbls PW	Volume Recovered: 60 bbls PW
Source of Release: Fittings/Connection	Date and Hour of Occurrence: 9-26-2017 9:00 am	Date and Hour of Discovery: 9-26-2017 9:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu/Amber Groves	
By Whom? Becky Haskell	Date and Hour: 9/26/2017 12:19 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 2:46 pm, Sep 29, 2017

Describe Cause of Problem and Remedial Action Taken.*



The release occurred when a 1" nipple on the water transfer filter malfunctioned. The nipple was replaced with a stainless steel nipple.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. Vacuum trucks were dispatched to recover all standing fluid. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: 	
Printed Name: Dakota Neel		
Title: HSE Coordinator	Approval Date: 9/29/2017	Expiration Date:
E-mail Address: dneel2@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: September 29, 2017 Phone: 575-746-2010		

* Attach Additional Sheets If Necessary

Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

nOY1727253282