

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC (OGRID #229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443
Facility Name: Stove Pipe Federal Com #002H	Facility Type: Tank Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-025-42926
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter B	Section 06	Township 25S	Range 35E	Feet from the 225	North/South Line North	Feet from the 1905	East/West Line East	County Lea
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	---------------

Latitude: 32.16610162 Longitude: -103.4041945 NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 25bbbls	Volume Recovered: 24.5bbbls
Source of Release: Tanks	Date and Hour of Occurrence: 10-30-2017	Date and Hour of Discovery: 10-30-2017 9:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Olivia Yu / Shelly Tucker	
By Whom?	Date and Hour: 10-30-2017 2:11 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By Olivia Yu at 2:20 pm, Nov 14, 2017



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a faulty level indicator/PLC alarm which failed to turn on the transfer pump causing the tanks to overflow. The level indicator and PLC were inspected and repaired.

Describe Area Affected and Cleanup Action Taken.*

The release occurred within the lined facility. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area evaluated for any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Aaron Lieb	Approved by Environmental Specialist: 	
Title: Senior HSE Coordinator	Approval Date: 11/14/2017	Expiration Date:
E-mail Address: alieb@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11-02-2017	Phone: 575-748-1553	

* Attach Additional Sheets If Necessary

Please inspect liner in question. Provide NMOCD with a concise report of the inspection with affirmation the liner has and will continue to contain liquids.

nOY1731852751