<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV
1220 S. St. Francis Dr. Santa Fe. NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Form C-141

Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Santa Fe, NM 87505													
Release Notification and Corrective Action													
						OPERATOR							
Name of Company: COG Production LLC [OGRID] 217955						Contact: Robert McNeill				тероп		Timal Report	
Address: 600 West Illinois Avenue, Midland TX 79701						Telephone No. 432-230-0077							
Facility Name: QUESO STATE #003H						Facility Type: Battery							
Surface Owner: State Mineral Owner						: State			API No. 30-025-42006				
				LOCA	ATIO	N OF REI	LEASE						
Unit Letter	Section	Township	Range	Feet from the		th/South Line Feet from the Ea			t/West Line County			nty	
P	36	23S	32E	400		South	1260		East		Lea		
Latitude 32.2551155 Longitude -103.6238022 NAD83													
NATURE OF RELEASE													
Type of Release:							Volume of Release:			Volume Recovered:			
Oil & Produced Water Source of Release:							4 bbls pw; 4 bbls oil Date and Hour of Occurrence:			3.75 bbls pw; 3.75 bbls oil Date and Hour of Discovery:			
Sight Glass										17 11:30 am			
Was Immediate Notice Given?							If YES, To Whom?						
			Yes 🗵	No 🛛 Not Re	equired								
By Whom? Was a Watercourse Reached?						Date and Hour: If YES, Volume Impacting the Watercourse.							
was a watercourse Reacned? ☐ Yes ☑ No						11 125, voidine impacing the watercourse.							
If a Watercon	urse was Im	pacted, Descri	be Fully.*										
			•			R	ECEIVED)					
By Olivia Yu at 9:25 am, Nov 16, 2017													
By Olivia Tu at 9.25 alli, NOV 10, 2017													
Describe Cause of Problem and Remedial Action Taken.*													
The release occurred when the sight glass broke on the production knockout. The sight glass has been replaced.													
Describe Area Affected and Cleanup Action Taken.*													
The release of	ocurred wit	hin the folcon	lined facil	ity Vacuum true	ke wor	a immadiataly	dispatched to reco	over all	standing fly	ide Conch	o will i	have the spill	
							on work plan to the						
remediation		•			•		1		11	•	,	C	
I haraby cart	ify that the i	nformation ai	van ahova	is true and compl	lata to t	the best of my	knowledge and u	ndorston	d that pure	uant to NM	OCD +	ules and	
							nd perform correc						
public health	or the envir	conment. The	acceptanc	e of a C-141 repo	ort by th	ne NMOCD m	arked as "Final Ro	eport" d	oes not reli	eve the ope	rator o	f liability	
							on that pose a three e the operator of i						
		vs and/or regu		tance of a C-141	тероп (uoes not renev	e the operator of i	responsi	office	mpnance v	viui aii	y oulei	
						OIL CONSERVATION DIVISION							
							Approved by Environmental Specialist:						
Signature:													
~-8						Approved by	Environmental S	peciansi		()			
Printed Nam	e: Dakota N	leel											
Title: HSE Coordinator							Approval Date: 11/16/2017			Expiration Date:			
E-mail Addr	ess: dneel2@	concho.com				Conditions of	Approval:				_		
E-mail Address: dneel2@concho.com						Conditions of Approval: Please inspect liner in question NMOCD with a concise report of			Provide	Attached			
Date: November /, 201 / Phone: 5/5-/46-2010													
Attach Additional Sheets II Necessaly						inspection with affirmation the liner has nOY1732034091							
ļ'										1326	J34U9T		

and will continue to contain liquids.