Form C-141 Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action							
	<b>OPERA</b>	TOR		Initial Repor	t 🛛 Final Report		
Name of Company: COG Operating, LLC (OGRID# 229137)         Contact: Robert McNeill							
Address: 600 West Illinois Avenue, Midland TX 79701Telephone No.: 432-683-7443Facility Name: Resolver Federal Com #002HFacility Type: Tank Battery							
	Facility Ty	be: Tank Datter	ſy				
Surface Owner: BLM Mineral Ov	wner: Federal	API No.: 30-025-42170					
LOCATION OF RELEASE							
Unit LetterSectionTownshipRangeFeet from theC1223S32E190	North/South Line North	Feet from the 2260	East/West I West	ine County	Lea		
Latitude: 32.325958 Longitude: -103.629583 NAD83							
	URE OF REL						
Type of Release: Oil & Produced Water		Volume of Release: Volume Recovered:					
		2bbls Oil & 21bbls PW			1.5bbls Oil & 20.5bbls PW		
Source of Release: Heater Treater	Date and I 2/13/2018	Hour of Occurrence		and Hour of I /2018 12:00pn			
Was Immediate Notice Given?	2/15/2018 If YES, To		2/13	/2010-12.00pl	11		
🗌 Yes 🛛 No 🖾 Not Req							
By Whom?	Date and I						
Was a Watercourse Reached?	If YES, V	olume Impacting	the Watercour	se.			
🗌 Yes 🖾 No							
If a Watercourse was Impacted, Describe Fully.*	(	40000					
		APPRO	VED				
Describe Cause of Problem and Remedial Action Taken.*				00 am, J	lun 22, 2018		
				<i>00 am</i> , J	lun 22, 2018		
A gasket on the clean out plate of a heater treater failed. The gasket	was replaced.			<i>00 am</i> , J	lun 22, 2018		
	was replaced.			00 am, J	lun 22, 2018		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in	spection has been c	By Olivia	Yu at 8:	p efforts made	at the above		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in- mentioned lined facility. Free fluids were removed and if present th	spection has been c e impacted gravel v	By Olivia onducted regardin was removed from	Yu at 8:	p efforts made	at the above		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final im- mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to h	spection has been c e impacted gravel v ave liner integrity	By Olivia onducted regardin vas removed from to contain free flu	Yu at 8:	p efforts made taken to a NM	at the above IOCD approved		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to he I hereby certify that the information given above is true and comple	spection has been c e impacted gravel v have liner integrity te to the best of my	<b>By Olivia</b> onducted regardir vas removed from to contain free flu	Yu at 8: ng the clean-up the liner and ids.	p efforts made taken to a NM t pursuant to N	at the above IOCD approved		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to he I hereby certify that the information given above is true and comple regulations all operators are required to report and/or file certain rel	spection has been c e impacted gravel v have liner integrity te to the best of my lease notifications a	onducted regardin vas removed from to contain free flu knowledge and u nd perform correct	Yu at 8: In the clean-up the liner and ids. Inderstand that ctive actions for	p efforts made taken to a NM t pursuant to N or releases whi	at the above IOCD approved IMOCD rules and ich may endanger		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to he I hereby certify that the information given above is true and comple	spection has been c e impacted gravel w have liner integrity te to the best of my lease notifications a t by the NMOCD n	<b>By Olivia</b> onducted regardir vas removed from to contain free flu whowledge and u nd perform correct parked as "Final R	Yu at 8: In the clean-up the liner and ids. understand that ctive actions for the port " does not	p efforts made taken to a NM t pursuant to N or releases whi ot relieve the o	at the above IOCD approved IMOCD rules and ich may endanger operator of liability		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to h I hereby certify that the information given above is true and comple regulations all operators are required to report and/or file certain rel public health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and rer or the environment. In addition, NMOCD acceptance of a C-141 re	spection has been c e impacted gravel w have liner integrity tet to the best of my lease notifications a t by the NMOCD n nediate contaminat	onducted regardin was removed from to contain free flu knowledge and u nd perform correct narked as "Final R ion that pose a thr	Yu at 8: In the liner and ids. Inderstand that tive actions for the port " does not eat to ground	p efforts made taken to a NM t pursuant to N or releases whi ot relieve the o water, surface	at the above IOCD approved IMOCD rules and ich may endanger perator of liability water, human health		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to h I hereby certify that the information given above is true and comple regulations all operators are required to report and/or file certain rel public health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and rer	spection has been c e impacted gravel w have liner integrity tet to the best of my lease notifications a t by the NMOCD n nediate contaminat	<b>By Olivia</b> onducted regardin was removed from to contain free flu where the operator of the operator of	Yu at 8: In the clean-up the liner and ids. Inderstand that cive actions for the port " does not reat to ground responsibility	p efforts made taken to a NM t pursuant to N or releases whi ot relieve the o water, surface for complianc	at the above IOCD approved IMOCD rules and ich may endanger operator of liability water, human health e with any other		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to h I hereby certify that the information given above is true and comple regulations all operators are required to report and/or file certain rel public health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and rer or the environment. In addition, NMOCD acceptance of a C-141 report	spection has been c e impacted gravel w have liner integrity tet to the best of my lease notifications a t by the NMOCD n nediate contaminat	<b>By Olivia</b> onducted regardin was removed from to contain free flu where the operator of the operator of	Yu at 8: In the clean-up the liner and ids. Inderstand that cive actions for the port " does not reat to ground responsibility	p efforts made taken to a NM t pursuant to N or releases whi ot relieve the o water, surface	at the above IOCD approved IMOCD rules and ich may endanger operator of liability water, human health e with any other		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final im- mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to he I hereby certify that the information given above is true and comple regulations all operators are required to report and/or file certain rel public health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and rer or the environment. In addition, NMOCD acceptance of a C-141 re federal, state, or local laws and/or regulations.	spection has been c e impacted gravel v have liner integrity te to the best of my lease notifications a t by the NMOCD n nediate contaminat eport does not reliev	By Olivia onducted regardin was removed from to contain free flu knowledge and u nd perform correct narked as "Final R ion that pose a thr ve the operator of OIL CON	Yu at 8: In the clean-up the liner and ids. Inderstand that trive actions for the port" does no reat to ground responsibility SERVATI	p efforts made taken to a NM t pursuant to N or releases whi ot relieve the o water, surface for complianc	at the above IOCD approved IMOCD rules and ich may endanger operator of liability water, human health e with any other		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to h I hereby certify that the information given above is true and comple regulations all operators are required to report and/or file certain rel public health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and rer or the environment. In addition, NMOCD acceptance of a C-141 re federal, state, or local laws and/or regulations.	spection has been c e impacted gravel v have liner integrity te to the best of my lease notifications a t by the NMOCD n nediate contaminat eport does not reliev	<b>By Olivia</b> onducted regardin was removed from to contain free flu where the operator of the operator of	Yu at 8: In the clean-up the liner and ids. Inderstand that trive actions for the port" does no reat to ground responsibility SERVATI	p efforts made taken to a NM t pursuant to N or releases whi ot relieve the o water, surface for complianc	at the above IOCD approved IMOCD rules and ich may endanger operator of liability water, human health e with any other		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to h I hereby certify that the information given above is true and comple regulations all operators are required to report and/or file certain rel public health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and rer or the environment. In addition, NMOCD acceptance of a C-141 re federal, state, or local laws and/or regulations.	spection has been c e impacted gravel v have liner integrity te to the best of my lease notifications a t by the NMOCD n nediate contaminat eport does not reliev	By Olivia onducted regardin was removed from to contain free flu knowledge and u nd perform correct narked as "Final R ion that pose a thr ve the operator of OIL CON	Yu at 8: In the clean-up the liner and ids. Inderstand that trive actions for the port" does no reat to ground responsibility SERVATI	p efforts made taken to a NM t pursuant to N or releases whi ot relieve the o water, surface for complianc	at the above IOCD approved IMOCD rules and ich may endanger operator of liability water, human health e with any other		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to h I hereby certify that the information given above is true and comple regulations all operators are required to report and/or file certain rel public health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and rer or the environment. In addition, NMOCD acceptance of a C-141 re federal, state, or local laws and/or regulations.	spection has been c e impacted gravel v have liner integrity te to the best of my lease notifications a t by the NMOCD n nediate contaminat eport does not reliev	By Olivia onducted regardin vas removed from to contain free flu r knowledge and u arked as "Final R ion that pose a thu ve the operator of OIL CON	Yu at 8: In the clean-up the liner and ids. Inderstand that ctive actions for teport" does no reat to ground responsibility SERVATI pecialist:	p efforts made taken to a NM t pursuant to N or releases whi ot relieve the o water, surface for complianc	at the above IOCD approved IMOCD rules and ich may endanger operator of liability water, human health e with any other		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to h I hereby certify that the information given above is true and comple regulations all operators are required to report and/or file certain rel public health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and rer or the environment. In addition, NMOCD acceptance of a C-141 re federal, state, or local laws and/or regulations.	spection has been c e impacted gravel v have liner integrity te to the best of my lease notifications a t by the NMOCD n nediate contaminat eport does not reliev	By Olivia onducted regardin was removed from to contain free flu where the operator of OIL CON	Yu at 8: In the liner and ids. Inderstand that tive actions for eat to ground responsibility <u>SERVATI</u> pecialist:	p efforts made taken to a NM t pursuant to N or releases whi ot relieve the o water, surface for complianc ON DIVIS	at the above IOCD approved IMOCD rules and ich may endanger operator of liability water, human health e with any other		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to h I hereby certify that the information given above is true and comple regulations all operators are required to report and/or file certain rel public health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and rer or the environment. In addition, NMOCD acceptance of a C-141 re federal, state, or local laws and/or regulations.	spection has been c e impacted gravel v have liner integrity t te to the best of my lease notifications a t by the NMOCD n nediate contaminat eport does not reliev	by Olivia onducted regardin was removed from to contain free flu where the operator of OIL CON Environmental S te: 6/22/201	Yu at 8: In the liner and ids. Inderstand that tive actions for eat to ground responsibility <u>SERVATI</u> pecialist:	p efforts made taken to a NM t pursuant to N or releases whi ot relieve the o water, surface for complianc ON DIVIS ON DIVIS	at the above IOCD approved IMOCD rules and the may endanger operator of liability water, human health e with any other ION		
A gasket on the clean out plate of a heater treater failed. The gasket Describe Area Affected and Cleanup Action Taken.* All of the fluid remained inside of the lined containment. A final in mentioned lined facility. Free fluids were removed and if present th disposal facility. The liner was inspected for damage and found to he I hereby certify that the information given above is true and comple regulations all operators are required to report and/or file certain rel public health or the environment. The acceptance of a C-141 report should their operations have failed to adequately investigate and rer or the environment. In addition, NMOCD acceptance of a C-141 re federal, state, or local laws and/or regulations.	spection has been c e impacted gravel v have liner integrity to te to the best of my ease notifications a t by the NMOCD n mediate contaminat eport does not reliev Approved by Approval Da	by Olivia onducted regardin was removed from to contain free flu where the operator of OIL CON Environmental S te: 6/22/201	Yu at 8: In the liner and ids. Inderstand that tive actions for eat to ground responsibility <u>SERVATI</u> pecialist:	p efforts made taken to a NM t pursuant to N or releases whi ot relieve the o water, surface for complianc ON DIVIS ON DIVIS	at the above IOCD approved IMOCD rules and the may endanger operator of liability water, human health e with any other ION		

From:	Yu, Olivia, EMNRD
То:	<u>"Dakota Neel"; stucker@blm.gov</u>
Cc:	James_Amos@blm.gov; Sheldon Hitchcock; Rebecca Haskell; Robert McNeill
Subject:	RE: (C-141 Final) Resolver Federal Com #002H (30-025-42170) 2-13-2018
Date:	Friday, June 22, 2018 8:04:00 AM
Attachments:	approved_(C-141 Final) Resolver Federal Com #002H (30-025-42170) 2-13-2018.pdf image004.png

Dear Mr. Neel:

The available information indicates **OPERATOR** has met the requirements of 19.15.29 NMAC and no further corrective action is required. NMOCD considers **nOY1804734766** closed. This determination by the Oil Conservation Division does not relieve Operator of responsibility should future information indicate a threat to ground water, surface water, human health, or the environment. Furthermore, it does not relieve Operator of responsibility for compliance with any federal, state, or local laws and/or regulations.

BLM like approval required.

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I <u>Olivia.yu@state.nm.us</u> 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Dakota Neel <DNeel2@concho.com>
Sent: Monday, March 5, 2018 5:24 PM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; stucker@blm.gov
Cc: James\_Amos@blm.gov; Billings, Bradford, EMNRD <Bradford.Billings@state.nm.us>; Sheldon Hitchcock
<SLHitchcock@concho.com>; Rebecca Haskell <RHaskell@concho.com>; Robert McNeill
<RMcNeill@concho.com>
Subject: (C-141 Final) Resolver Federal Com #002H (30-025-42170) 2-13-2018

## Ms. Yu/Ms. Tucker,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank You,

Dakota Neel HSE Coordinator COG Operating LLC Cell: <u>432-215-2783</u> <u>dneel2@concho.com</u>

2407 Pecos Ave.

## Artesia, NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.

From:	Tucker, Shelly
To:	Dakota Neel
Cc:	Yu, Olivia, EMNRD; James Amos@blm.gov; Billings, Bradford, EMNRD; Sheldon Hitchcock; Rebecca Haskell; Robert McNeill
Subject:	Re: (C-141 Final) Resolver Federal Com #002H (30-025-42170) 2-13-2018
Date:	Wednesday, April 18, 2018 12:38:36 PM
Attachments:	image001.png

## **Resolver Federal Com #002H \*\* API 30-025-42170 \*\* DOR 2-13-2018**

BLM accepts your Final C-141. Like approval from NMOCD is required as well.

NOTE: LPC Timing Stipulations are in effect - from March 1st through June 15th. Please plan remedial activities accordingly. Check for African Rue...treat (before it gets out of control).

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker Environmental Protection Specialist **O&G Spill/Release Coordinator** 

575.234.5905 - Direct 575.361.0084 - Cellular 575.234.6235 - Emergency Spill Number

stucker@blm.gov

**Bureau of Land Management** 620 E. Greene St Carlsbad, NM 88220

The BLM acceptance/approval does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event a site does not achieve successful restoration, or future issues with contaminants are encountered, the operator will be asked to address these issues until they are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Mon, Mar 5, 2018 at 5:24 PM, Dakota Neel <<u>DNeel2@concho.com</u>> wrote:

Ms. Yu/Ms. Tucker,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank You,

Dakota Neel HSE Coordinator **COG Operating LLC** 

Cell: 432-215-2783

dneel2@concho.com

2407 Pecos Ave.

Artesia , NM 88210



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.