

CONDITIONS OF APPROVAL

API #	Operator	Well name & Number
30-025-46397	Goodnight Midstream Permian	Robinson State SWD # 001

Applicable conditions of approval marked with **XXXXXX**

Administrative Orders Required

XXXXXXX	Review administrative order when approved for additional conditions of approval

Other wells

Casing

XXXXXXX	SURFACE & PRODUCTION CASING - Cement must circulate to surface --
XXXXXXX	Surface casing must be set 25' below top of Rustler Anhydrite in order to seal off protectable water. Approximate depth Rustler Anhydrite is 1540 feet

Lost Circulation

XXXXXXX	Must notify OCD Hobbs Office if lost circulation is encountered at 575-370-3186

Stage Tool

XXXXXXX	Must notify OCD Hobbs Office prior to running Stage Tool at 575-370-3186
XXXXXXX	If using Stage Tool on Surface casing, Stage Tool must be greater than 350' and a minimum 200 feet above surface shoe.
XXXXXXX	When using a Stage Tool on Intermediate or Production Casing Stage must be a minimum of 50 feet below previous casing shoe.

Completion & Injection

XXXXXXX	In addition to the mud log required by R-20863 a set of geophysical logs will be run to demonstrate upper and lower contacts of the Glorieta Formation prior to running casing. Prior to perforating please submit copies of logs to the district geologist in Hobbs and the Engineering Bureau in Santa Fe.
XXXXXXX	Will require a deviational survey with the C-105
XXXXXXX	Must notify Hobbs OCD office prior to conducting MIT (575) 393-6161
XXXXXXX	Must conduct & pass MIT prior to any injection
XXXXXXX	Approval of this APD does not approve your tubing sizes. Please see SWD order for approved tubing sizes.
XXXXXXX	Must conduct & pass MIT prior to any injection