Submit 1 Copy Office	1 Copy To Appropriate District State of New Mexico						Form C-103	
<u>District I</u> – (575) 393-6161 Energy, N		Energy, Mir	Ainerals and Natural Resources		WELL API		Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			CEDIA TION	30-025-353				
811 S. First St., Artesia, NM 88210 OIL CON			SERVATION		5. Indicate	Type of Lea	ase	
1000 Rio Brazo	2t III – (505) 334-6178 Rio Brazos Rd., Aztec, NM 87410 St IV – (505) 476-3460 Santa Fe, NM 87505				STAT		FEE	
<u>District IV</u> – (50 1220 S. St. Fran 87505	05) 476-3460 ncis Dr., Santa Fe, NM	Sal	ilia re, inivi o	7303	6. State Oil	& Gas Lea	se No.	
07303	SUNDRY NOTIC	ES AND REPOR	TS ON WELLS	}	7. Lease Na	me or Unit	Agreement Name	
	THIS FORM FOR PROPOSA ESERVOIR. USE "APPLICA		" (FORM C-101) FO	OR SUCH	OUTLAN	ND STATE I	UNIT	
1. Type of V	Well: Oil Well 🔲 🔾	Gas Well X Oth	ner pl	EC OCD HOBB	8. Well Nur			
CHISHOLM ENERGY OPERATING, LLC					372137			
3. Address of Operator 801 CHERRY STREET, SUITE 1200-UNIT 20						10. Pool name or Wildcat		
FORT WORTH, TX 76102						OSUDO ATOKA GAS, SOUTHWEST		
	Letter U ::		n the SOUTH	I line and6		et from the		
Sect	tion 1	Township	-1	Range 34E	NMPM	Cor	_{unty} LEA	
		11. Elevation (<i>Sl</i> 3695		, RKB, RT, GR, etc.,)			
	12. Check Ap	ppropriate Box	to Indicate N	fature of Notice,	Report or O	ther Data	ı	
	NOTICE OF INT	ENTION TO:		SUB	SEQUENT	REPOR	RT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING								
TEMPORARILY ABANDON ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐ CASING/CEMENT JOB ☐								
	TER CASING COMMINGLE	MULTIPLE COM	PL 📙	CASING/CEMEN	I JOB	Ш		
	OOP SYSTEM							
OTHER:				OTHER:				
	ribe proposed or comple							
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.								
03/16/2020-CHISHOLM ENERGY OPERATING, LLC RESPECTFULLY REQUESTS TO TA THE OUTLAND STATE UNIT 4								
(30-025-35343) IN ORDER TO FURTHER EXAMINE THE UPHOLE POTENTIAL. PLEASE SEE TA PROCEDURE AND WELLBORE								
DIAGR	RAM ATTACHED.							
PROCE	EDURE: MIRU PULLING	UNIT						
PULL TBNG RU WIRELINE AND SET CIBP AT 12254'MD (50' ABOVE TOP OF TOP PERF)								
	BAIL 35' OF CMNT ON							
GIVE N	NMOCD DIST. 2 OFFICE	48 HR NOTICE O	F PRESSURE TE	ST				
PRESSURE TEST CSG FOR 30 MIN W/ LESS THAN 10% PRESSURE DROP								
Spud Date:	02/01/2001		Rig Release Da	nte:				
I hamahar aamtif	ry that the information al	hove is two and a	ammlata to the h	act of my Imagelada	a and haliaf			
I nereby certii	y that the information at	bove is true and co	ompiete to the b	est of my knowledg	e and belief.			
SIGNATURE	and the S		TITLE SR.	REGULATORY TEC	ч	DATE	03/16/2020	
SIGNATUKE	Gennifer E	V/X/M	_			DATE		
	name <u>JENNIFER ELRO</u>)D	_ E-mail address	s: <u>jelrod@chisholm</u>	energy.com	_ PHONE	: 817-953-3728	
For State Use	e Only							
APPROVED :	BY: Fin	-	TITLE			DATE	03/17/2020	
Conditions of Approval (if any):								

