Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District I – (575)</u> 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised July 18, 2013 WELL API NO.
District II - (575) 748-1283	OIL CONSERVATION DIVISION		30-025-37161
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505		STATE FEE S 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	Fe, NM		
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			
PROPOSALS.)		W H TURNER 8. Well Number 3	
1. Type of Well: Oil Well Gas Well Other 2. Name of Operator Gas Well Other		9. OGRID Number	
GRIZZLY OPERATING, LLC			258350
3. Address of Operator 5847 SAN FELIDE STE 2000 HOUSTON TEXAS 77057		10. Pool name or Wildcat TUBB; BLINEBRY; PADDOCK	
5847 SAN FELIPE, STE. 3000, HOUSTON, TEXAS, 77057 4. Well Location		I UBB; BLINEBR I; PADDOCK	
Unit Letter_Kfeet from the SOUTH line and2,270feet from theWESTline			
Section 29 Township 21S Range 37E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3,483' GR			
12 Charle Appropriate Pay to Indicate Nature of Nation Papart or Other Data			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK PLUG AND ABANDON COMMENCE DRIL COMMENCE DRIL COMMENCE DRIL		<u> </u>	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT			
CLOSED-LOOP SYSTEM	_		_
OTHER:	nlatad anomationa (Clearly state all)	OTHER:	give portigent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
Grizzly Operating, LLC requests to temporarily abandon (TA) this well to evaluate any future uphole recompletion opportunities and			
preserve remaining future reserves by not prematurely plugging and abandoning this well. TA procedure as follows:			
 MIRU WS. LD production equipment. RU WL. Set CIBP @ 5,000' (top perf @ 5,092'). Cap w/ 35' of cmt via bailer. 			
3. Contact NMOCD to schedule MIT. Fill casing with treated water and pressure test to 500 psig for at least 30 minutes. Record			
pressure chart.			
 RD WL & WS. File subsequent C-103 and 	copy of MIT chart.		
or inobaccequent e res una	oopy of Mill onald.		Condition of Approval: notify
			OCD Hobbs office 24 hours
Spud Date:	Rig Release Da	te:	rior of running MIT Test & Chart
		P	IN OLIMINIG MAL
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE Kull J. SIGNATURE TITLE DATE DATE DATE DATE			
Type or print name Kyle Zimmermann E-mail address: kzimmerman@grizzlyenergyllc.com PHONE: 432-202-0145 Ean State Use On but E-mail address: kzimmerman@grizzlyenergyllc.com PHONE: 432-202-0145			
For State Use Only			
APPROVED BY: KING JUTTLE Compliance Officer A DATE 10/22/20			
Conditions of Approval (if any)			



