Submit 1 Copy To Appropriate District  State of New Mexico	OCB- RECEIVED 10/22/20 Form C-103
Office State of New Minards and Natural Decourses	Revised August 1, 2011
District I – (575) 393-6161 Energy, Minerals and Natural Resources	WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	30-025-28362
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
District III – (505) 334-6178 1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV = (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
District IV – (505) 476-3460  1220 S. St. Francis Dr., Santa Fe, NM	N/A
87505	IV/A
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	South Hobbs (G/SA) Unit
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	, , ,
PROPOSALS.)  1. Type of Well: Oil Well Gas Well Other Temporarily Abandoned	8. Well Number 159
1. Type of Well: Oil Well Gas Well Other Temporarily Abandoned	
2. Name of Operator	9. OGRID Number: 157984
Occidental Permian Ltd.	
3. Address of Operator	10. Pool name or Wildcat:
P.O. Box 4294, Houston, Tx 77210	Hobbs (G/SA)
	110000 (0,011)
4. Well Location (Surface)	
Unit LetterF_:2335feet from the _North line and1675	feet from theWestline
Section 9 Township 19S Range 38	E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, or	etc.)
3596' (GL)	
12. Charle Ammoniata Day to Indicate Nature of Nation	Danaut ou Othan Data
12. Check Appropriate Box to Indicate Nature of Notice	e, Report of Other Data
NOTICE OF INTENTION TO:	JBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☑ PLUG AND ABANDON ☐ REMEDIAL W	<del>-</del>
	DRILLING OPNS. P AND A
PULL OR ALTER CASING	ENT JOB
DOWNHOLE COMMINGLE	
DOWN I I OLE COMMINGEE	
_	
OTHER: OTHER:	
OTHER: OTHER:  OTHER: OTHER:  OTHER:  OTHER:	
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple	
OTHER: OTHER:  OTHER: OTHER:  OTHER:  OTHER:	
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.	Completions: Attach wellbore diagram of Ouring this procedure we plan to use
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone	Ouring this procedure we plan to use the closed-loop system with a steel
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  RUPU. POOH with ESP  RIH with packer and plug to isolate water zone  Set CIBP and CICR, Squeeze zone1 with thixotropic cement	Ouring this procedure we plan to use the closed-loop system with a steel
OTHER:  I. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  RUPU. POOH with ESP  RIH with packer and plug to isolate water zone Set CIBP and CICR, Squeeze zone1 with thixotropic cement Drill out and pressure test squeeze	Ouring this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required
OTHER:  OTHER:  OTHER:  OTHER:  OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement	Ouring this procedure we plan to use the closed-loop system with a steel
OTHER:  I. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  RUPU. POOH with ESP  RIH with packer and plug to isolate water zone Set CIBP and CICR, Squeeze zone1 with thixotropic cement Drill out and pressure test squeeze	Ouring this procedure we plan to use he closed-loop system with a steel ank and haul contents to the required
OTHER:  I. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  RUPU. POOH with ESP  RIH with packer and plug to isolate water zone Set CIBP and CICR, Squeeze zone1 with thixotropic cement Drill out and pressure test squeeze	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17
OTHER:  I. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  RUPU. POOH with ESP  RIH with packer and plug to isolate water zone Set CIBP and CICR, Squeeze zone1 with thixotropic cement Drill out and pressure test squeeze	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17
OTHER:  I. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  RUPU. POOH with ESP  RIH with packer and plug to isolate water zone Set CIBP and CICR, Squeeze zone1 with thixotropic cement Drill out and pressure test squeeze	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify
OTHER:  I. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  RUPU. POOH with ESP  RIH with packer and plug to isolate water zone Set CIBP and CICR, Squeeze zone1 with thixotropic cement Drill out and pressure test squeeze	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO	Ouring this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours
OTHER:  I. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  RUPU. POOH with ESP  RIH with packer and plug to isolate water zone Set CIBP and CICR, Squeeze zone1 with thixotropic cement Drill out and pressure test squeeze	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO	Ouring this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO  Rig Release Date:	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO  Rig Release Date:	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO  Spud Date:  Rig Release Date:	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart edge and belief.
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO  Spud Date:  Rig Release Date:	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my knowledges.  SIGNATURE  TITLE Production Engineer	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart edge and belief.  DATE 10/15/2020
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my knowledges.  SIGNATURE  TITLE Production Engineer	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart edge and belief.
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my knowledges of the production Engineer  Type or print name Faris Al Ismaili E-mail address faris al ismaili@	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart edge and belief.  DATE 10/15/2020
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my knowledge of the production and pressure tests of the production of the produc	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart edge and belief.  DATE 10/15/2020
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO  Spud Date:  Rig Release Date:  Title Production Engineer  Type or print name Faris Al Ismaili E-mail address faris al ismaili@  For State Use Only	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart  Edge and belief.  DATE 10/15/2020  Oxy.com PHONE: 832-973-0186
OTHER:  13. Describe proposed or completed operations. (Clearly state all pertinent details, of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple proposed completion or recompletion.  1. RUPU. POOH with ESP 2. RIH with packer and plug to isolate water zone 3. Set CIBP and CICR, Squeeze zone1 with thixotropic cement 4. Drill out and pressure test squeeze 5. Run new ESP, RDMO  Spud Date:  Rig Release Date:  I hereby certify that the information above is true and complete to the best of my knowledge or print name  Faris Al Ismaili  For State Use Only  SEE RULE 19.15.7.14 NMAC. For Multiple proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple prop	Completions: Attach wellbore diagram of During this procedure we plan to use the closed-loop system with a steel ank and haul contents to the required disposal per ODC Rule 19.15.17  Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart edge and belief.  DATE 10/15/2020