Submit 1 Copy To Appropriate District Office		DCD- RECEIVED 11/23/20 Form C-103 Revised July 18, 2013
District I – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1292		WELL API NO. 30-041-20943
511 5. 1 list St., Altesia, 100 66210	ONSERVATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	220 South St. Francis Dr. Santa Fe, NM 87505	STATE 🗌 FEE 📈
1220 S. St. Francis Dr., Santa Fe, NM 87505		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name
		Mustang Sally
1. Type of Well: Oil Well 🔽 Gas Well 🗌 Other		8. Well Number 001
2. Name of Operator Armstrong Energy Corporation		9. OGRID Number 1092
3. Address of Operator		10. Pool name or Wildcat
PO Box 1973 Roswell, NM 88202		Wildcat; Fusselman
4. Well Location Unit Letter N : 461 fee	et from the South line and	2085 _{feet from the} West _{line}
	wenship 5S Range 34E	NMPM Roosevelt County
	n (Show whether DR, RKB, RT, GR, etc	.)
	4332' GR	
12. Check Appropriate	Box to Indicate Nature of Notice,	, Report or Other Data
NOTICE OF INTENTION	TO: SUE	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK 🖉 PLUG AND ABANDON 🗌 REMEDIAL WORK 🗌 ALTERING CASIN		
TEMPORARILY ABANDON CHANGE P		
PULL OR ALTER CASING		NT JOB
CLOSED-LOOP SYSTEM		
OTHER:	OTHER:	
of starting any proposed work). SEE RUI		nd give pertinent dates, including estimated date ompletions: Attach wellbore diagram of
proposed completion or recompletion. Anticipated wellbore prep procedure to prepare	for sidetrack at later date	
1. Rig up PU and NU BOP 2. PU workstring and TIH with 5.5" packer. Set		
Establish injection rate and pump 100 sx classical	ss H cement plug, squeeze through/around fi	sh @ 6135'
4. Leave top of plug @ 6,000', WOC 5. Tag plug		
 TOOH w/tubing, ND BOP and remove 5.5" c Free-point casing and determine where to cu 	it off.	
8. Cut 5.5" casing with jet cutter and pull, antici 9. TOOH w/casing and LD	pate from approximately 5,500°	
10. Reassemble wellhead and NU BOP. 11. TIH w/tubing and spot 500' cement kick off	plug from 3172' to 2672' in 7.875" open hole.	
12. WOC 13. Tag plug, dress plug for directional when dr	illing rig arrives.	
14. NDBOP, RDMO		
Spud Date: 5/3/2011	Rig Release Date: 6/3/2011	
5/5/2011	0/3/2011	
I hereby certify that the information above is true a	nd complete to the best of my knowled	ge and belief.
	- • •	
SIGNATURE	TITLE VP Engineering	10/2/20
Type or print name Kyle Alpers	E-mail address: kalpers@ae	ecnm.com PHONE: 575-625-2222
For State Use Only		110112
APPROVED BY: Flant	TITLE	DATE 12/01/2020
Conditions of Approval (if any):		





