(DO NOT USE THIS FORM FOR PROPO	State of New Mexico Energy, Minerals and Natural Resou OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505 ICES AND REPORTS ON WELLS DIVISION FOR PERMIT (FORM C-101) FOR SUCH Gas Well Other	WELL API NO. 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name
4 Wall Location		
4. Well Location Unit Letter ::	feet from the line	andfeet from theline
Section Section	Township Range	NMPM County
Scction	11. Elevation (Show whether DR, RKB, RT,	3
	11. Zie ration (Show whether DR, RRB, RT,	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK		
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE alicia fulto	TITLE	DATE
Type or print name For State Use Only	E-mail address:	PHONE:
APPROVED BY: Conditions of Approval (if any):	TITLE Compliance Of	DATE 12/3/20

November 6th, 2020

NMGSAU #347 API # 30-025-38452


Lea County, NM

Production Casing: 5-1/2" 17# Surface Casing: 8-5/8" 24#

Objective: Reactive in Grayburg

Procedure:

- 1. MIRU WO Unit
- 2. PU and RIH w/ tubing
- 3. CO CIBP and cmt, tag PBTD of ~3,912'
- 4. POOH, lay down collars, swab test
- 5. If swab test is good (if not go to step 6)
 - a. Per @ 2 SPF from 3815' 3890'
 - b. Sonic Hammer all perfs with 3000 gal
 - c. Continue at Step 7
- 6. If swab test yields too much water or San Andres water
 - a. Set CIBP @ 3885'
 - b. Perf @ 2 SPF from 3815' 3865'
 - c. Sonic Hammer all perfs with 3000 gal
- 7. POOH with sonic hammer, swab test
- 8. RIH with rods or ESP based on swab results
- 9. RTP
- 10. RDMO WO Unit



Apache Corporation – NMGSAU #347 GL=3677' Wellbore Diagram - Current Status KB=3688' Date: 2/12/2014 Spud: 12/7/07 API: 30-025-38452 R. Taylor **Surface Location** 170' FNL & 2370' FWL, Unit C Sec 19, T19S, R37E, Lea County, NM Hole Size **Surface Casing** =11" 8-5/8" 24# K-55 @ 1300' w/ 700 sx to surface TOC @ 1150' Ratty CMT from 1200-2400 Produced 3765'-76' from 1/08-7/08 Produced 3890'-98' from 7/08-6/09 TA'd 6/09 MKR JT @ 3479 1/08: Perf Grayburg @ 3765-76 w/ 2 jspf (23 holes). Acidized w/ 1500 gal 15% NEFE acid. swab water 7/08: SOZ'd all perfs w/ 400 sxs 6/09: Set CIBP @ 3850 w/30' cmt. Well TA'd 7/08: Perf Grayburg @ 3890-98 w/ 2 jspf (16 holes). Acidized w/ 1500 gal 15% NEFE acid. 1/08: Perf Grayburg @ 3890-3905; 3918-34 w/ 2 jspf (64 holes). Acidized w/ 2000 gal 15% NEFE acid. Bad emulsion 1/08: Pump 55 gal 2827, 55 gal DM046, 55 gal 2827 chemical 7/08: SQZ'd 7/08: Perf Grayburg @ 3918-34 w/ 2 jspf (32 holes). Acidized w/ 2000 gal 15% NEFE acid. Swab BLK water. SQZ'd w/ 137 sxs 7/08: cmt 7/08: Perf Grayburg @ 3956-62; 3970-74 w/ 2 jspf (22 holes). Acidized w/ 1500 rtn @ btm gal 15% NEFE acid. SQZ'd w/ 161 sxs 3950' 1/08: Perf Grayburg @ 3970-93 w/ 2 jspf (47 holes). Acidized w/ 2000 gal 15% NEFE acid. swab water 7/08: SQZ'd Hole Size 1/08: Perf Grayburg @ 4030-45 w/ 2 jspf (31 holes). Acidized w/ 2000 gal 15% NEFE acid. swab water =7-7/8" 7/08: SOZ'd **Production Casing** PBTD = 3909' MD5-1/2" 17# K-55 @ 4110' w/ 900 sxs to surface TD = 4110' MD