Submit 1 Copy To Appropriate District Office	State of New Mexico	Received NMOCD 12/28/20 Form C-103	
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-31114	
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	<ul> <li>5. Indicate Type of Lease STATE FEE</li> <li>6. State Oil &amp; Gas Lease No.</li> <li>VB-698</li> </ul>	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505		
1220 S. St. Francis Dr., Santa Fe, NM 87505			
(DO NOT USE THIS FORM FOR PROPO	ICES AND REPORTS ON WELLS ISALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name <b>Dolphin State</b>	
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.) 1. Type of Well: Oil Well 🔀	CATION FOR PERMIT" (FORM C-101) FOR SUCH Gas Well	8. Well Number 2	
2. Name of Operator		9. OGRID Number	
Mack Energy Corporation		013837	
3. Address of Operator		10. Pool name or Wildcat	
P.O. Box 960 Artesia,NM 88210		Wildcat San Andres	
4. Well Location			
	<b>1980</b> feet from the <b>S</b> line and <b>1980</b>	feet from theEline	
Section 16	Township 16S Range 33E	NMPM County Lea	
Section 10	11. Elevation (Show whether DR, RKB, RT, GR,		
	4229' GR	, eic.)	
	-		
NOTICE OF IN	PLUG AND ABANDON	SUBSEQUENT REPORT OF: WORK	
NOTICE OF IN PERFORM REMEDIAL WORK [] TEMPORARILY ABANDON [] PULL OR ALTER CASING [] DOWNHOLE COMMINGLE [] CLOSED-LOOP SYSTEM []	ITENTION TO:     S       PLUG AND ABANDON     REMEDIAL V       CHANGE PLANS     COMMENCE       MULTIPLE COMPL     CASING/CEI	SUBSEQUENT REPORT OF:         WORK <ul> <li>ALTERING CASING</li> <li>E DRILLING OPNS.</li> <li>P AND A</li> <li>Image: Second Second</li></ul>	
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER:	ITENTION TO:       S         PLUG AND ABANDON       REMEDIAL V         CHANGE PLANS       COMMENCE         MULTIPLE COMPL       CASING/CEI         OTHER:       COMMENCE	SUBSEQUENT REPORT OF: WORK	
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp	ITENTION TO:       S         PLUG AND ABANDON       REMEDIAL V         CHANGE PLANS       COMMENCE         MULTIPLE COMPL       CASING/CEI         Deted operations.       Clearly state all pertinent detail         ork).       SEE RULE 19.15.7.14 NMAC.       For Multiple	SUBSEQUENT REPORT OF:         WORK       ALTERING CASING         E DRILLING OPNS.       P AND A         MENT JOB       PNE         Is, and give pertinent dates, including estimated da	
NOTICE OF IN PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp of starting any proposed wo proposed completion or rec 9/22/20 MIRU plugging equipmer og. And Tag @ 4967. 09/23/20 Ci ressured up to 500 psi. Spot 35 sx of VOC. 09/24/20 Tagged plug @ 23 00 psi. Spotted 55 sx class C @ 52. 5". Mixed and pumped 20 sx class	ITENTION TO:       PLUG AND ABANDON       REMEDIAL W         CHANGE PLANS       COMMENCE         MULTIPLE COMPL       CASING/CEI         Deted operations.       OTHER:         obleted operations.       Clearly state all pertinent detail         ork).       SEE RULE 19.15.7.14 NMAC.       For Multiple         completion.       MULTIPLE OSO psi. Spot 25 sclass C w/ 2% CACL @ 4602-4252.       WOC. Tagge	SUBSEQUENT REPORT OF:         WORK       ALTERING CASING         E DRILLING OPNS.       P AND A         MENT JOB       PNF         Is, and give pertinent dates, including estimated date completions: Attach wellbore diagram of         g and tag @ 4967. (existing CIBP in hole). RIH w/ sx Class C @ 4967-4717. Perf'd casing @ 4548'.         ed @ 4225'. Spot 25 sx class C @ 2625-2375.         35. Perf 4 ½ csg @ 450'. Pressured up on perfs to and backhoe. Cut off wellhead. Cement had fallen Dug up anchors. Welded on "Above Ground Dry	
NOTICE OF IN PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp of starting any proposed wo proposed completion or rec 9/22/20 MIRU plugging equipmer og. And Tag @ 4967. 09/23/20 Ci ressured up to 500 psi. Spot 35 sx of VOC. 09/24/20 Tagged plug @ 23 00 psi. Spotted 55 sx class C @ 52. 5". Mixed and pumped 20 sx class	ITENTION TO:       PLUG AND ABANDON         PLUG AND ABANDON       COMMENCE         CHANGE PLANS       COMMENCE         MULTIPLE COMPL       OTHER:         oleted operations.       OTHER:         oleted operations.       (Clearly state all pertinent detail ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.         nt. ND wellhead. NU BOP. RIH w/ 4 ½ gauge ring rc. Hole w/ MLF. Pressure up to 500 psi. Spot 25 sclass C w/ 2% CACL @ 4602-4252. WOC. Tagge 565'. Spot 25 sx class C w/ 2% CACL @ 1685-143         5 to surface. RDMO.       09/28/20 Moved in welder at C cement 35 to surface in 4 ½ and 13 3/8 casing. I g up and removed anchors. Cleaned location and mathematical structure in the	SUBSEQUENT REPORT OF:         WORK       ALTERING CASING         E DRILLING OPNS.       P AND A         MENT JOB       PNI         Is, and give pertinent dates, including estimated da         e Completions: Attach wellbore diagram of         g and tag @ 4967. (existing CIBP in hole). RIH w/         sx Class C @ 4967-4717. Perf'd casing @ 4548'         ed @ 4225'. Spot 25 sx class C @ 2625-2375.         35. Perf 4 ½ csg @ 450'. Pressured up on perfs to and backhoe. Cut off wellhead. Cement had fallen Dug up anchors. Welded on "Above Ground Dry	
NOTICE OF IN PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp of starting any proposed wo proposed completion or rec 9/22/20 MIRU plugging equipmer og. And Tag @ 4967. 09/23/20 Ci ressured up to 500 psi. Spot 35 sx of VOC. 09/24/20 Tagged plug @ 23 00 psi. Spotted 55 sx class C @ 52. 5". Mixed and pumped 20 sx class	ITENTION TO:       PLUG AND ABANDON         PLUG AND ABANDON       COMMENCE         CHANGE PLANS       COMMENCE         MULTIPLE COMPL       OTHER:         oleted operations.       OTHER:         oleted operations.       (Clearly state all pertinent detail ork). SEE RULE 19.15.7.14 NMAC. For Multiple completion.         nt. ND wellhead. NU BOP. RIH w/ 4 ½ gauge ring rc. Hole w/ MLF. Pressure up to 500 psi. Spot 25 sclass C w/ 2% CACL @ 4602-4252. WOC. Tagge 565'. Spot 25 sx class C w/ 2% CACL @ 1685-143         5 to surface. RDMO.       09/28/20 Moved in welder at C cement 35 to surface in 4 ½ and 13 3/8 casing. I g up and removed anchors. Cleaned location and mathematical structure in the	SUBSEQUENT REPORT OF:         WORK       ALTERING CASING         E DRILLING OPNS.       P AND A         MENT JOB       PNI         Is, and give pertinent dates, including estimated da       PNI         g and tag @ 4967. (existing CIBP in hole). RIH w/       SX Class C @ 4967-4717. Perf'd casing @ 4548'         ed @ 4225'. Spot 25 sx class C @ 2625-2375.       S5. Perf 4 ½ csg @ 450'. Pressured up on perfs to and backhoe. Cut off wellhead. Cement had fallen         Dug up anchors. Welded on "Above Ground Dry noved off.       State of the state	
NOTICE OF IN PERFORM REMEDIAL WORK  TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM OTHER: 13. Describe proposed or comp of starting any proposed wo proposed completion or rec 9/22/20 MIRU plugging equipmer og. And Tag @ 4967. 09/23/20 Ci ressured up to 500 psi. Spot 35 sx of VOC. 09/24/20 Tagged plug @ 23 00 psi. Spotted 55 sx class C @ 52. 5". Mixed and pumped 20 sx class Iole Marker". Backfilled cellar. Du	ITENTION TO:       PLUG AND ABANDON       REMEDIAL V         CHANGE PLANS       COMMENCE         MULTIPLE COMPL       OTHER:         bleted operations. (Clearly state all pertinent detail         brk). SEE RULE 19.15.7.14 NMAC. For Multiple         completion.         nt. ND wellhead. NU BOP. RIH w/ 4 ½ gauge ring         rc. Hole w/ MLF. Pressure up to 500 psi. Spot 25 s         class C w/ 2% CACL @ 4602-4252. WOC. Tagge         Sto surface. RDMO. 09/28/20 Moved in welder at         C cement 35 to surface in 4 ½ and 13 3/8 casing. I         g up and removed anchors. Cleaned location and n	SUBSEQUENT REPORT OF:         WORK       ALTERING CASING         E DRILLING OPNS.       P AND A         MENT JOB       PNF         Is, and give pertinent dates, including estimated da         e Completions:       Attach wellbore diagram of         g and tag @ 4967. (existing CIBP in hole). RIH w/         sx Class C @ 4967-4717. Perf'd casing @ 4548'.         ed @ 4225'. Spot 25 sx class C @ 2625-2375.         35. Perf 4 ½ csg @ 450'. Pressured up on perfs to and backhoe. Cut off wellhead. Cement had fallen         Dug up anchors. Welded on "Above Ground Dry noved off.	

SIGNATURE J <i>erry W. Sherrell</i>	_ TITLE Production Clerk]	DATE_12/29/2020
Type or print name For State Use Only	E-mail address:	PHONE:
	TITLE Compliance Officer A	DATE <u>12/28/20</u>