Susana Martinez

Governor

HOBBS OCD

John H. Bemis

Cabinet Secretary - Designee

Brett F. Woods, Ph.D. **Deputy Cabinet Secretary**

Jami Bailey **Division Director** Oil Conservation Division



Response Required - Deadline Enclosed

Underground Injection Control Program "Protecting Our Underground Sources of Drinking

31-Jul-12

CHEVRON USA INC. ATTN: REGULATORY & COMPLIANCE 15 SMITH ROAD MIDLAND, TX 79705

LETTER OF VIOLATION and SHUT-IN DIRECTIVE **Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

WEST DOLLARHIDE DRINKARD UNIT No.122

30-025-31489-00-00

Active Injection - (All Types)

K-32-24S-38E

Test Date: Test Reason: 7/30/2012

Permitted Injection PSI:

Actual PSI:

Repair Due:

11/2/2012

Test Type:

Comments on MIT:

Annual IMIT

Bradenhead Test

Test Result:

FAIL TYPE: Other Internal Failure

FAIL CAUSE: FAILED BRADENHEAD TEST***CASING SHOWED 1500#; TUBING SHOWED 1500#;

OPERATOR IN VIOLATION OF NMOCD RULE 19.15.26.11*

Oil Conservation Division 1625 N. French Drive • Hobbs, New Mexico 88240 Phone (575) 393-6161 • Fax (575) 393-0720 • www.emnrd.state.nm.us/OCD



WEST DOLLARHIDE DRINKARD UNIT No.131

30-025-31995-00-00

Active Injection - (All Types)

H-32-24S-38E

Test Date:

7/31/2012

Permitted Injection PSI:

Actual PSI:

Test Reason:

5-year Test

Test Result:

Repair Due:

11/3/2012

Test Type:

Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT:

WHILE LOADING WELL FOR PRESSURE TEST WELL COMMENCED TO PRESSURE UP TO 200#. WELL WOULD NOT FULLY LOAD TO RUN PRESSURE TEST CHART ***OPERATOR IN

VIOLATION OF NMOCD RULE 19.15.26.11**** FAILED PRESSURE TEST****

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



015H14150977

\$0.45

07/31/12

Marled From 88240

CHEVRON USA INC. ATTN: MIKE ARCHER P.O. DRAWER 2 ANDREWS, TX 79714

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



015H14150977 \$0.45 07/31/12 Mailed From 88240

US POSTAGE

CHEVRON USA INC. ATTN: REGULATORY & COMPLIANCE 15 SMITH ROAD MIDLAND, TX 79705