ubmit 1 Copy To Appropriate District State of New Mexico			Form C-103
Office	Ce Enormy Minorala and Natural Pasauraa		Revised August 1, 2011
District 1 – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 882140BBS OCD IL CONSERVATION DIVISION District III – (505) 334 6178			30-025-39746
1000 Bio Brazos Rd Aztec NM 87410		5. Indicate Type of Lease STATE X FEE	
		7505	6. State Oil & Gas Lease No.
$\frac{District IV}{District IV} = (505) 476-3460$ 1220 S. St. Francis Dr., Santa Fe, NOV 1 4 2012 87505 Santa Fe, NM 87505			E-9713
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name PEDRO 11 STATE	
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other			8. Well Number
2. Name of Operator			9. OGRID Number
MANZANO, LLC			231429
3. Address of Operator		10. Pool name or Wildcat San Andres	
P.O.BOX 2107, ROSWELL, NM 88202-2107			MESCALERO UPPRER RENN NORTH
4. Well Location			
Unit Letter F 2025 feet from theNORTH_line and1985 feet from the WEST_line Section 11 Township 10S Range 32E NMPM LEA County			
	A	RKB, RT, GR, etc.)	
4269' GL	(Snon mienie 21,		الم المحمد ال المحمد المحمد المحمد المحمد المحمد
12. Check Appropriate B	ox to Indicate N	ature of Notice, I	Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI			
	OMPL	CASING/CEMENT	JOB
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
Well is no longer capable of production. Propose to plug and abandon as follows: Set 100' cement plug from 3866'-3966' across liner top.			
Set 100' cement plug from 3326-3426' across 8 5/8" shoe. Tag plug.			
Set 100' cement plug from 376'-426 across 13 3/8" shoe. Tag plug.			
Set 10 sack plug at surface. From 60 - Surface			
Install dry hole marker. Clean location including meter pole, notify LeaCo Electric to remove all power poles.			
Spud Date:	Rig Release Da	ite: 7.0(.2010	
5-31-2010		7-06-2010	
		· · · · · · · · · · · · · · · · · · ·	
I hereby certify that the information above is true and	d complete to the be	est of my knowledge	and belief.
			1 1
SIGNATURE (and Kaydaly	TITLE_OTHE	R	DATE11/12/2012
0			
Type or print namePAUL RAGSDALE E-mail address: paul@manzanoenergy.com PHONE: _575-626-7903 For State Use Only			
		= /	
APPROVED BY Jonacha		ST. MGE	DATE/1-20-2012
Conditions of Approval (if any);			
Oil Conservation Division - Hobbs office Must be Notifi	ind		
24 hours prior to the beginning of Plugging Operations	begin.		
·	J		
			NOV 2. 8 2012 Chm

•

MANZANG - LLC WELLBORE Diagram (as of 11/15/12)



