

Submit One Copy To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

Revised November 3, 2011

HOBBS OCD

OIL CONSERVATION DIVISION

NOV 14 2012

1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-35110 ✓
1. Type of Well: <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator XTO Energy, Inc. ✓		6. State Oil & Gas Lease No.
3. Address of Operator 200 North Loraine, Ste. 800 Midland, Texas 79701		7. Lease Name or Unit Agreement Name TexMack 5 State ✓
4. Well Location Unit Letter <u>W</u> : <u>990</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>East</u> line Section <u>5</u> Township <u>16 S</u> Range <u>32 E</u> NMPM <u> </u> County <u>Lea</u>		8. Well Number <u>002</u> ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4347' GL		9. OGRID Number 005380 ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

☒ Location is ready for OCD inspection after P&A

- X All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.
X Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.
X A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.

- X The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.
X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.
N/A If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)
X All other environmental concerns have been addressed as per OCD rules.
X Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.
X If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE Gene Hudson TITLE: Maintenance Foreman

DATE: 11/14/2012

TYPE OR PRINT NAME: Gene Hudson

E-MAIL: richard_hudson@xtoenergy.com

PHONE: 575-441-1634

For State Use Only APPROVED

BY: Mary S Brown

TITLE Compliance Officer

DATE 11/20/2012 Conditions of

Approval (if any):

NOV 29 2012