
Office	State of Ne			Form C-103
District I - (575) 393-6161	Energy, Minerals and	d Natural Resources	WELL API NO.	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	EMEDNSERVA	TION DIVIGION		
811 S. First St., Artesia, NM 88210	MODEKVA 1220 Couth C	HON DIVISION	J. maieute Type of De	
811 S. First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 8741 NOV 2 <u>District IV</u> – (505) 476-3460	1 2012 South S	i. Francis Dr.	STATE	FEE BLM
1220 S. St. Francis Dr., Santa Fe, National Control	Santa Fe, I	NIVI 873U3	6. State Oil & Gas Lea	se No.
8/505	ES AND REPORTS ON V	VELLS	7. Lease Name or Uni	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICA"	LS TO DRILL OR TO DEEPEN	OR PLUG BACK TO A	Maljamar AGI	Agreement Ivanie
PROPOSALS.)			8. Well Number	
1. Type of Well: Oil Well G		Gas Injection	9. OGRID Number	
2. Name of Operator Frontier Field Services, LLC			221115	
3. Address of Operator 4200 Skelly I	Or, St. 700, Tulsa OK 741	35	10. Pool name or Wild Wildcat (Lower Wolfc	
4. Well Location				
Unit LetterO_:	130 _feet from the			
Section 21		7S Range	32E NMPM	County Lea
	11. Elevation <i>(Show wheth</i> 4016 GL	ner DR, RKB, RT, GR,	, elc.)	
12 Check An	propriate Box to India	rate Nature of Not	ice, Report or Other Data	a a
•	• .•			
NOTICE OF INTI PERFORM REMEDIAL WORK ☐ I	<u> </u>	REMEDIAL V	SUBSEQUENT REPOR Nork 🛭 ALT	RT OF. ERING CASING 🗌
	_	-	DRILLING OPNS. PAI	
PULL OR ALTER CASING 🔲 1		CASING/CE	MENT JOB	
DOWNHOLE COMMINGLE				
OTHER:	1	OTHER:	⊠ h2s sign installatio	n per NMOCD order
13. Describe proposed or complet of starting any proposed work proposed completion or recomposed completion or recomposed completion.). SEE RULE 19.15.7.14	ate all pertinent detail	s, and give pertinent dates, inc	cluding estimated date
on November 15-17, 2012, Geolex per or Permit to Drill and the Conditions of enetrate the Frontier AGI #1 injection commission Division Order. Details for	of Approval. On November zone that are located with or these activities are included.	er 12-14, 2012, Geole in ½ mile of the AGI	x installed H_2S signs at each G #1 in accordance with the Ne	of the 8 wells that w Mexico Oil
₂ S Sign Installation, Frontier AGI #1,	Maijamar, NM.			
oud Date:	Rig Rele	ease Date:		
nereby certify that the information abo	ove is true and complete to	the best of my know	rledge and belief.	
		·		
				· · · 1
GNATURE_	TITLE: Preside	ent, Geolex, Inc Co	nsultant for Frontier DATE:	11/21/2012
/pe or print name: Alberto A. Gutier	<u>ez, CPG</u> E-mail address:	aag@geolex.com P	HONE: <u>505-842-8000</u>	
or State Use Only		0-1-	<u> </u>	
PPROVED B	TITLE	LIST.M	DATE /	11-21-201
onditions of Approval (if any):)			NOV 2 9 2012 ()
(1 - 12 - 12 - 12 - 12 - 12 - 12 - 12 -



Field Activity Report

For

Drill Pad Remediation and H₂S Sign Installation Frontier AGI #1, Maljamar, NM

November 20, 2012

Geolex supervised the drilling pad downsizing and remediation and the placement of H₂S warning signs on wells that penetrate the injection zone in accordance with the Conditions of Approval and the NM OCD Order, respectively. PB Energy contracted SWEATT Construction to perform the excavation and restoration activities. Geolex geologist, Tom Sharp, directed the work to ensure the work was completed in accordance with the Application for Permit to Drill (APD), the COA for the APD, and the Frontier Field Services, LLC requirements, and the NM OCD Order. Plans were adjusted at the request of Frontier's Construction Supervisor, Jeff Bowman, to allow for a fence and gate on the northeast side of the pad and to tie the drilling pad into the compressor station pad.

Prior to beginning work, a safety meeting was conducted and utilities in the vicinity of the work area were cleared. Three pipelines run east-west under the pad several feet below the native desert topography. No excavating below native topography was conducted in the vicinity of the pipelines.

The scope of work required the removal of caliche on the north, east and south sides of the drilling pad and restoring the surface with native sand to match the existing dune structure. The south side of the pad was cut and the cut material (native sand) was used to fill the north side of the pad to match existing dunes. There is no topsoil in the area of the site, therefore, no topsoil was placed in the restoration areas. The north access road was moved 15 feet to the east for adequate room for truck entrance that will avoid the H₂S monitors.

The caliche was initially excavated and stockpiled with a Caterpillar D-6 dozer on November 15, 2012. On November 16, 2012, a frontend loader and two end-dump trucks were used to load and transport the caliche to the new parking lot construction area located northwest of the flare. No soil was transported off-site.

The sand below the caliche on the south side was ripped, stockpiled, loaded, and transported to the north side fill area. A water truck was used to control dust and to add moisture for soil compaction. On November 17, 2012, the frontend loader spread the sand on the north side to match existing dunes. The sides of the pad were sloped at a low angle to match the existing dune structure and to slow erosion. The sand was moistened and compacted by wheel rolling with the frontend loader. No compaction testing was performed.

The prior and final site configurations are shown in attached Figure 1. All applicable requests of the Pecos District Conditions of Approval (COA) have been completed in accordance with Section IX: Interim Reclamation, page 13; except for seeding the reclaimed areas. Seed will be placed on the restored areas at a later date and prior to spring 2013.

In addition to completing the drill pad remediation, Geolex posted H₂S warning signs at the 8 wells within a half mile that penetrate the injection zone to satisfy the requirements of the NM OCD Order (Figure 2 and photos).


These wells include:

Federal B1 #001 SWD 29 #001 Federal Hudson #001 Hudson #1 Baish A #14 Baish A #12 Elvis #2 Elvis #4 RECEIVED
NOV 2 | 2012
HOBBSOCD


The first two wells on the list, Federal B1 #001 and SWD 29 #001, already had the required signs; therefore, no signs were installed at these two wells (see attached photos).

Photographic documentation of the above activities is included with this letter.


Photos of Drilling Pad Downsizing and Reclamation Construction




Removing surface caliche layer from the north side of the drill pad





Stockpiling caliche next to the access road







Water truck watering and compacting temporarary access along flare fence











View of north fill area after caliche was remove and native sand deposited




South cut area after removing stockpiled sand




View of east slope pipeline marker





View of north remediated area with access road





View of northeast corner after remediation












Photos of H2S Signs at 8 Wells Penetrating the Injection Zone



Federal B1 #001



SWD 29 #001



Hudson Federal #001




Hudson #1



Baish A #12



Baish A #14



Elvis #2

