field salt water to test RBP to 500	
top perforation. or/oxygen scavenger (packer fluid).	office
Submit chart to NMOCD Hobbs	OCD District of Pressure Test
	ΑĞ
elief.	il. Notii
DATE	ns of Approval. prior to runnin
com PHONE: (432)688-9174	ns of / prior
DATE/2-17-201	Conditions of Approval: 24 hours prior to running
DEC 1.2 2012	

Submit 1 Copy To Appropriate District	State of New M	1exico		Form C-103
Office <u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Na	,	WELL API NO.	Revised August 1, 2011
	REGIETONSTRVATIO	N DIVISION	30-	025-03071
<u>District III</u> – (505) 334-6178	1220 South St. Fr	ancis Dr	5. Indicate Type of	_ease
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	UEC 11 Zusanta Fe, NM	87505	S. Indicate Type of I STATE X	ease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	しははらしてり		By3140	
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA	ES AND REPORTS ON WELL ILS TO DRILL OR TO DEEPEN OR P TION FOR PERMIT" (FORM C-101)	LS PLUG BADD TO BE SUC	7. Lease Name or U Maeuum Abo Unit Tr	nit Agreement Name act 13
PROPOSALS.) 1. Type of Well: Oil Well G	as Well Other		8. Well Number 0	13 -
2 Name of Operator			9. OGRID Number	
ConocoPhillips 2. Address a Constator			10. Pool name or W	217817 /
3. Address of Operator P. O. Box 518 Midland, TX	310 79710		Vacuum; Abo Reef	IIIIcat
4. Well Location			vacuum, Abb Reel	
Unit Letter I : 23	feet from the South	line and 660	feet from t	he Eastline
Section 5		Range 35E	NMPM C	County LEA
Street 2 h and a second street and a second st	11. Elevation (Show whether D. 3944' GR	R, RKB, RT, GR, etc.)		
	2)11 GR			<u> </u>
12. Check Ap	propriate Box to Indicate	Nature of Notice, 1	Report or Other Da	ita
NOTICE OF INT	ENTION TO:	l gur	SEQUENT REPO	NRT OF:
	PLUG AND ABANDON []	REMEDIAL WOR		TERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRII		AND A
	MULTIPLE COMPL	CASING/CEMENT	JOB 🔲 .	
DOWNHOLE COMMINGLE				
OTHER:	<u> </u>	OTHER:		
 Describe proposed or complet of starting any proposed work proposed completion or recon). SEE RULE 19.15.7.14 NMA			
Placed call to EL Gonzales w/OCD Attached is a current wellbore schen		is well to place well in	TA status per followi	ng procedures.
ConocoPhillips would like to place t	his well in TA status to save the	e well for uphole poter	ıtal.	
1. Run bit & scraper to 8250'.			•	•
2. Run RBP and packer to test casing	g. Set RBP @ 8250', pick up &	set packer. Load tubii	ng with field salt water	to test RBP to 500
psig Load annulus with field salt was 3. TOOH. Install setting tool on tubi		∕a ~ 8225-8230' withi	n 50 of ton nerforation	1
4. Load hole with FSW to test plug.	Displace FSW with fresh water	containing corrosion	inhibitor/oxygen scave	nger (packer fluid).
5. POOH & lay down work string. M6. Contact NMOCD to witness MIT.	love off location. RLI HPPT and conduct/chart	550 neig MIT for 22 n	rinutae Cuhmit chart t	o NMOCD Hobbo
office.	RO THE F and conductional .	550 psig 1411 101 52 11	imutes, Buomit Chaig (3 MMOCD HOUS
Spud Date:	Rig Release I	Date:		
				n. enger (packer fluid). o NMOCD Hobbs
I hereby certify that the information about	ove is true and complete to the	hest of my knowledge	and helief	
		oost of my knowledge	und bonon	TE: <u>(432)688-9174</u>
CIGNATURE TAR) Acces and the contract of th	name of the	274 £ 2444	
SIGNATURE Mand	JITLE Staff	Regulatory Technicia	n DATE	
Type or print name Rhonda Rogers	E-mail addre	ss: <u>rogerrs@conocop</u>	hillips.com PHON	TE: <u>(432)688-9174</u>
For State Use Only	1 1	,		.9

APPROVED BY:
Conditions of Approval (if any):

ConocoPhillips

Schematic - Current VACUUM ABO UNIT 013-013

