Submit 3 Copies To Appropriate District State of New Mexico	Form C-103
	June 19, 2008
District I 1625 N. French Dr., Hobbs, NM 87240 Energy, Minerals and Natural Resources	WELL API NO.
District II OIL CONSERVATION DIVISION	<u>30-025-40368</u>
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV	STATE X FEE
1220 S. St. Francis Dr., Santa F RECEIVED 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name:
PROPOSALS.)	Black Bear 36 State
1. Type of Well:	8. Well Number
Oil Well X Gas Well Other 2. Name of Operator	1H 9. OGRID Number
E0G Resources, Inc.	7377
3. Address of Operator	10, Pool name or Wildcat
P.O. Box 2267 Midland, TX 79702	Red Hills: BS Upper Shale
4. Well Location	
Unit Letter0 300feet from theSouth line and	2190 feet from the East line
Section 36 Township 25S Range 33E	NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, e	etc.)
3321' <u>GR</u>	
12. Check Appropriate Box to Indicate Nature of Notice,	-
NOTICE OF INTENTION TO: SUE	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK 📋 PLUG AND ABANDON 🛄 REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILI	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILI	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL	LING OPNS. P AND A JOB
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	LING OPNS. P AND A JOB Stimated date
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE OTHER: OTHER: complete 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact	LING OPNS. P AND A JOB Sive pertinent dates, including estimated date ch wellbore diagram of proposed completion
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE OTHER: OTHER: completed 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 10/10/12 10/10/12 MIRU to frac. Begin 16 stage frac. 10/12/12 Finish 16 stage frac. Perforated from 9896 to 14189', 0.3 Frac w/ 5361 bbls 7.5% HC1 acid, 2291680 lbs 100 mesh sand	LING OPNS. P AND A JOB X etion X give pertinent dates, including estimated date ch wellbore diagram of proposed completion 39", 602 holes. d, 3713005 lbs 40/70 sand.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE OTHER: OTHER: completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 10/10/12 MIRU to frac. Begin 16 stage frac. 10/12/12 Finish 16 stage frac. Perforated from 9896 to 14189', 0.3 Frac w/ 5361 bb1s 7.5% HCl acid, 2291680 lbs 100 mesh sand 118760 bb1s total load. 11/01/12 RIH to drill out plugs and clean out well. 11/04/12 Finish drill and clean out. Flowback. 11/05/12 RIH w/ 2-7/8" production tubing and gas lift assembly set	LING OPNS. P AND A JOB Science P AND A JOB Science P AND A sive pertinent dates, including estimated date ch wellbore diagram of proposed completion 39", 602 holes. d, 3713005 lbs 40/70 sand,
 TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT. DOWNHOLE COMMINGLE COMPL OTHER: OTHER: Completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 10/10/12 MIRU to frac. Begin 16 stage frac. 10/12/12 Finish 16 stage frac. Perforated from 9896 to 14189', 0.3 Frac w/ 5361 bbls 7.5% HCl acid, 2291680 lbs 100 mesh sand 118760 bbls total load. 11/01/12 RIH to drill out plugs and clean out well. 11/05/12 RIH w/ 2-7/8" production tubing and gas lift assembly set 11/09/12 Turned to sales. 	LING OPNS. P AND A JOB X etion X give pertinent dates, including estimated date ch wellbore diagram of proposed completion 39", 602 holes. d, 3713005 lbs 40/70 sand, at 9433'. Flowback. 8/31/12
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE OTHER: OTHER: completed OTHER: OTHER: completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 10/10/12 10/10/12 MIRU to frac. Begin 16 stage frac. 10/12/12 10/10/12 Finish 16 stage frac. Perforated from 9896 to 14189', 0.3 Frac w/ 5361 bbls 7.5% HCl acid, 2291680 lbs 100 mesh sand 118760 bbls total load. 11/01/12 RIH to drill out plugs and clean out well. 11/04/12 11/05/12 RIH w/ 2-7/8" production tubing and gas lift assembly set 11/09/12 Turned to sales. Spud Date: 8/11/12 Rig Release Date: Image: Release Date:	LING OPNS. P AND A JOB X etion X give pertinent dates, including estimated date ch wellbore diagram of proposed completion 39", 602 holes. d, 3713005 lbs 40/70 sand, at 9433'. Flowback. 8/31/12
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE OTHER: OTHER: complete OTHER: OTHER: complete OTHER: complete 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attact or recompletion. 10/10/12 10/10/12 MIRU to frac. Begin 16 stage frac. 10/12/12 10/12/12 Finish 16 stage frac. Perforated from 9896 to 14189', 0.3 Frac w/ 5361 bbls 7.5% HCl acid, 2291680 lbs 100 mesh sand 118760 bbls total load. 11/01/12 RIH to drill out plugs and clean out well. 11/04/12 Finish drill and clean out. Flowback. 11/09/12 RIH w/ 2-7/8" production tubing and gas lift assembly set 11/09/12 Turned to sales. Spud Date: 8/11/12 Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge.	LING OPNS. P AND A JOB X sive pertinent dates, including estimated date ch wellbore diagram of proposed completion 39", 602 holes. d, 3713005 lbs 40/70 sand, at 9433'. Flowback. 8/31/12 lge and belief.
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT. DOWNHOLE COMMINGLE OTHER: OTHER: completion 13. Describe proposed or completed operations. (Clearly state all pertinent details, and g of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attac or recompletion. 10/10/12 10/10/12 MIRU to frac. Begin 16 stage frac. 10/12/12 Finish 16 stage frac. 10/12/12 Finish 16 stage frac. Perforated from 9896 to 14189', 0.3 Frac w/ 5361 bbls 7.5% HCl acid, 2291680 lbs 100 mesh sand 118760 bbls total load. 11/01/12 RIH to drill out plugs and clean out well. 11/04/12 Finish drill and clean out. Flowback. 11/05/12 RIH w/ 2-7/8" production tubing and gas lift assembly set 11/09/12 Turned to sales. Spud Date: 8/11/12 Rig Release Date: SIGNATURE Max Amagement of the best of my knowledgement of the best of the best of my knowledgement of the best of the be	LING OPNS. P AND A JOB etion X give pertinent dates, including estimated date ch wellbore diagram of proposed completion 39", 602 holes. d, 3713005 lbs 40/70 sand, at 9433'. Flowback. 8/31/12 lge and belief. ory Analyst DATE 11/15/12 PHONE 432-686-3689