HOBBS OCD

Form 3160-5 (March 2012)

DEPARTMENT OF THE INTERIOR DEC 1 4 2012 **UNITED STATES** BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

Expires: October 31, 2014 5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELCEIVED OCD Hobber 18 161 August 1816 August 1

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals 6. If Indian, Allottee or Tribe Name

ubandoned wen.	0301 01111 0100 0 ()	The sacin proposa				
	T IN TRIPLICATE – Other	7. If Unit of CA/Agreement, Name and/or No. WBDU				
1. Type of Well				8. Well Name and No.		
Oil Well Gas V	Well Other	West Blinebry Drinkard Unit (WBDU) #049 (37346)				
2. Name of Operator Apache Corporation		9. API Well No. 30-025-37743				
3a. Address 3b. Phone No. (include area code)				· · · · ·		
303 Veterans Airpark Lane, Suite 3000 Midland, TX 79705	432/818-1062		Eunice; B-T-D, North (22900)			
4. Location of Well (Footage, Sec., T.	,R.,M., or Survey Description		11. County or Parish, State			
1330' FSL & 2400' FEL UL J Sec 9 T21S R37	E P		Lea County, NM			
12. CHE	CK THE APPROPRIATE BO	OX(ES) TO INDICATE NATUR	RE OF NOTIC	E, REPORT OR OTH	ER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
✓ Notice of Intent	Acidize	Deepen	Production (Start/Resume)		Water Shut-Off	
Notice of Intent	Alter Casing		Reclamation		Well Integrity	
Subsequent Report	Casing Repair	New Construction	Recomplete		Other ADD PAY &	
	Change Plans	Plug and Abandon	Temp	orarily Abandon	RE-FRAC	
Final Abandonment Notice	Convert to Injection	Plug Back	☐ Water	r Disposal		
the proposal is to deepen direction	nally or recomplete horizonta		d measured an	d true vertical depths of		

Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Apache intends to add pay and re-frac the Drinkard, as detailed on the attached procedure.

SEE ATTACHED FOR **CONDITIONS OF APPROVAL**

accept for record

14. I hereby certify that the foregoing is true and correct. Name (Printed/	Typed)							
Reesa Holland		Title Sr. Staff Reg Tech						
Signature Relsa Holand	Date	10/04/2012						
THIS SPACE F	OR FEDERAL	OR STATE OFFICE USE	APPROVED					
Approved by			GES 1 5 2019					
		Title	Pate DEC 1 3 2012					
Conditions of approval, if any, are attached. Approval of this notice does not that the applicant holds legal or equitable title to those rights in the subject entitle the applicant to conduct operations thereon.	Office	Genula Mount	~ T					
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a c	crime for any person k	nowingly and willfully to make to any	Henartment Aldigered of the United States an	v false				
fictitious or fraudulent statements or representations as to any matter with			Control of the office butter in	7 13150				

CORPORATION

WBDU #49 – Add Pay & Re-frac

Recommended Procedure

- 1. MIRU. POOH w/rods & pump. Install BOP. TFF and POOH w/2-7/8" tbg.
- 2. RIH w/4-3/4" bit, csg scraper and 2-7/8" tbg. RIH to +/-6895' PBTD. Clean well out to +/-6750' if necessary. POOH.
- 3. RU wireline unit. NOTE: All perfs picked from the Halliburton Spectral Density/Dual-Spaced Neutron Log run 9/3/2006.
- 4. Perforate the Drinkard II-V intervals @ 6569', 71', 75', 77', 79', 84', 97', 99', 6607', 14', 33', 35', 43', 45', 59', 71', 75', 80', 85', 87', 89', 6701', 05', 07', 09', 11', 13' & 15' w/2 spf, 120 deg phasing. (Total = 56 shots).
- 5. RIH w/treating pkr on 3-1/2", N-80 ws. Set pkr @ +/- 6450'.
- Acidize the Drinkard II-V intervals w/4,200 gals 15% HCI-NE-FE BXDX acid & ball sealers. Release pkr & run through perfs to knock off balls. Re-set pkr @ +/- 6450'.
- 7. Pump 1 drum corrosion inhibitor and 2 drums scale inhibitor ahead of frac.
- 8. RU frac equipment. Frac the Drinkard II-V intervals w/100,000# 20/40 SLC (or equivalent) resin coated sand down 3-1/2" ws @ 30+ BPM in 35# XL gel as per frac rec.
- 9. Rel pkr & POOH LD 3-1/2 ws.
- 10. RIH w/bit on 2-7/8" tbg. Clean well out to PBTD @ +/- 6895'. POOH.
- 11. RIH w/SN & 2-7/8" prod tbg to +/-6750'.
- 12. RIH w/1-1/2" pump & rods.
- 13. Return to production. Place well in test.

WELL DATA SHEET

Last Update: 12-29-08

Lease Nan	ne: WB	DU #49 (Han	KB-1 477) API No: 30-025-37743
Location:	13305/29 Sw-Sw-M	400'E 'w-SE Sec 9 T-2	215, R-37.E County: Lea ST: MM
1			
77	11	~ Toce 590'	Spud Date: 8-22-06 Well Elev: 3490 GL 10 KB TD Date: 9-2-06 Completion Date: 10-4-06
		!	TD: 6950' PBTD: 6895' TOC: 590'CBL
		Casing	Producing Formation: Blinebry Tubb/Drinkard
			Perfs: From 5672 to 5833 2/spf 6589 to 6656-2586
			6/29 to 6278' z/spf to
			IP:BOPDBWPDMCF/D
			Well History: (See Atrached)
		Cmt: 5755x	
		(Circ)	
H		Blinebry	
1 1		5672-76	
	.	5714-18"	
	1+	5829-33'	
		Tubb	
		6129-33'	
		6227-31	
		Drinkard	
	. +	-	Well Equipment:
	E	1 19 0 44 -40	Pumping Unit:
	/2	Wt: 17#	Tbg: 207 Jts 278' Size (Feet Grade
	0	J-55 Grd:4-80	Motor Type: HP: 40 POC: Tbg: 207 Jts 275' Size 5.5" Grade MA@ 6746' SN@ 6725' TAC@ 5622' (10-2-0)
	_	Doth: 60 co	Rods: 72-1" KD + 78-76" KP + 116-214" KD
10.	2-1	Cmt 140	Pump: 2" x 11/2" x 25" RHBC (10-3-06
689	200	CIIII. <u>/ 7005K</u>	1 min. 2 ×1 - × 27 ×100 (10-3-0)

TD: 6950'